

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PW200-178R1

Service Tool: PWC42077 Rev. A

Description: Puller

Effectivity: PW206A, PW206B, PW206B2, PW206B3, PW206C, PW206E, PW207C, PW207D, PW207D1, PW207D2, PW207E, PW207K

Subject: Tool Obsolete

Reason:

Problem: Tool is a manual powered puller, hydraulic power is required.

Cause: Force required to remove Bearing.

Solution: Obsolete, PWC42077 is replaced by PWC65669 top race puller, PWC42105 is replaced by PWC65516 bottom race puller. Both replacement pullers require the use of new reaction pad PWC65517.

WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to:
VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.

Issued: Jun 09/2011
Revised: Oct 17/2022

PWC42077
Page 1 of 3

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PW200-178R1

Instruction: Not applicable.

Compliance: Required

Tool Usage: Overhaul

Tool Disposition: Discard do not use for any application.

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Jun 09/2011
Revised: Oct 17/2022

PWC42077
Page 2 of 3

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PW200-178R1

TSB Revision Notes			
TSB	DATE	Tool Rev No.	CHANGES
PW200-178	10/2022	1	Added PWC42105 to clarify that it is replaced by PWC65516. Solution info moved to instruction and instruction clarified.

ICN-00198-G000124836-001-01

Figure 1

P&WC Proprietary Information. Subject to the restrictions on the first page.

Issued: Jun 09/2011
Revised: Oct 17/2022

PWC42077
Page 3 of 3