



Rolls-Royce

ADVANCED RELEASE

TO: Holders of RR300 Series Operations and Maintenance Manual, Publication CSP 21009.

Reason: Revised inspection procedure.

Component: Compressor Front Mating Ring Seal

Remarks: Contact Rolls-Royce

72-30-15-200-801

Jul 31/23



COMPRESSOR FRONT MATING RING SEAL INSPECTION/CHECK

TASK 72-30-15-200-801

1. Do the Inspection of the Compressor Front Mating Ring Seal

A. General

This task gives you the procedure to do the inspection of the compressor front mating ring seal.

B. Materials

None

C. Consumable Materials

None

D. Expendable Parts

None

E. Special Tools and Equipment

None

F. References

None

G. Procedure

SUBTASK 72-30-15-220-001



REF. FIG. 801/TASK 72-30-15-990-801

(1) Do the visual inspection of the compressor front mating ring seal.

(a) Do a visual inspection of the compressor front mating ring seal to the limits that follow:

ITEM	SERVICEABLE LIMITS	REPAIR LIMITS	ACTION NECESSARY
Seal face			
- Nicks, scratches or burrs	None permitted.	Not repairable.	Replace the compressor front mating ring seal.

EFFECTIVITY: ALL



SECTION B-B

ii00022945

Compressor Front Mating Seal Ring - Inspection/Check
FIG. 801/TASK 72-30-15-990-801

EFFECTIVITY: ALL