

# TASK CARD

Sub-Task NUMBER		REFERENCE	DEFECT/WORK REQUIRED	RECTIFICATION DETAILS		Performed By:	Released (CRS) By:
292722861		SB 292 72 2861	SB 292 72 2861, ACCESSORY GEARBOX FRONT COVER. DETECTION OF WEAR ON THE 41- OR 42-TOOTH GEAR FRONT BEARING HOUSING.	<p>PERFORMED SB 292 72 2861, ACCESSORY GEARBOX FRONT COVER DETECTION OF WEAR ON THE 41- OR 42- TOOTH GEAR FRONT BEARING HOUSING. FOUND BOTH LH + RH FOWERZ INSPECTION RESULTS COMPLIANT (≤ 0.15mm), REFER ATTACHED COMPLIANT CERTIFICATE.</p> <p>REMOVED ITEMS P/N &amp; S/N : N/A</p> <p>INSTALLED ITEMS P/N &amp; S/N : N/A</p> <p>REMARK: N/A</p> <p>NON SERIAL ITEMS USED P/N : N/A</p>		PS	PS
292732822		SB 292 73 2822	SB 292 73 2822, VISUAL INSPECTION OF ADJUSTED HYDROMECHANICAL METERING UNIT (HMU) DRIVE-LINK SPLINES.	<p>PERFORMED SB 292 73 2822, VISUAL INSPECTION OF ADJUSTED HYDROMECHANICAL METERING UNIT (HMU) DRIVE LINK SPLINES. FOUND BOTH HMU SPLINT COMPLIANT. REFER ATTACHED COMPLIANT CERTIFICATE.</p> <p>REMOVED ITEMS P/N &amp; S/N 0292 861 920 SN: 40140 (LH) 6292 961 920 SN: 33001 (RH)</p> <p>INSTALLED ITEMS P/N &amp; S/N 0292 861 920 SN: 40140 (LH) 0292 861 920 SN: 33001 (RH)</p> <p>REMARK: N/A</p> <p>NON SERIAL ITEMS USED P/N : N/A</p>		PS	PS
292732869		SB 292 73 2869	SB 292 73 2869, CHECK OF THE PRE-BLOCKAGE PRESSURE SWITCH OF THE FUEL FILTER.	<p>CHECK OF THE PRE-BLOCKAGE PRESSURE SWITCH OF THE FUEL FILTER CARRIED OUT. N.A. W/SB 292 73 2869 FOUND SATIS.</p> <p>REMOVED ITEMS P/N &amp; S/N : N/A</p> <p>INSTALLED ITEMS P/N &amp; S/N P/N: JAP05926 1. LH. S/N: 10999 2. RH S/N: 11091</p> <p>REMARK: N/A</p> <p>NON SERIAL ITEMS USED P/N : N/A</p>		PS	PS

The work recorded above has been carried out in accordance with the requirement of the FAA airworthiness regulations for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.