



SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
LYCOMING SB 642A  INCORRECT PISTON AND RING COMBINATION	Not Applicable	-	-	-	-	NOT APPLICABLE 

Linked To:	9M-AMA
Based On:	Not Applicable ▼
Warning:	0
Warning Unit:	Select ▼
Completed:	
Due At:	-
Status:	NOT APPLICABLE ▼
Limitation Notes:	<p>REFER TIC-R44-21-0005 DATE 18 JUN 2021</p> <p>NOT APPLICABLE DUE ENGINE MODEL O-540-F1B5 INSTALLED.</p>