

SB RR300-73-008, NEW ISSUE

Aeronet Galaxy aerospace2 > Modifications > Edit - Mozilla Firefox

https://galaxy.aerospace2.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&templ...

AD/SB ID: 3633 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ENGINE, FUEL AND CONTROL - ADDITION OF MINIMUM STOP SCREW TO FUEL CONTROL ASSEMBLY

Title/Subject: SB RR300-73-008, NEW ISSUE

Version No:

Reason For Raising:

URL:

Date: 24 / 06 / 2016

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename
	SB RR300-73-008	3633-1513.pdf

AD/SB ID: 3633 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BGG	Engine1 Hours	-	Hours	50	0.00 ↗	2000.00 ↗	TO BE COMPLETED	