

P&WC 11524 (2021-07) MRO Information Management (9290)

S.I.L. NO. **GEN-169R1**

SERVICE INFORMATION LETTER

WARNING - PROPRIETARY RIGHTS NOTICE

This document is the property of Pratt & Whitney Canada Corp. ("P&WC"). You may not possess, use, copy or disclose this document or any information in it, for any purpose, including without limitation to design, manufacture, or repair parts, or obtain FAA or other government approval to do so, without P&WC's express written permission. Neither receipt nor possession of this document alone, from any source, constitutes such permission. Possession, use, copying or disclosure by anyone without P&WC's express written permission is not authorized and may result in criminal or civil liability.

Subject: P&WC Generation 3 Recorder End of New Production

Applicability: All Engine Families

This Service Information Letter (SIL) is issued to inform owners, operators, and maintainers about the end of new production of the P&WC Generation 3 (Gen3) and older recorders. This SIL applies to aircraft applications equipped with the following recorders:

Data Transmission Unit (DTU),
ADAS: ADAS+, ADAS Plus Upgrade, ADASh, ADASd,
Intellistart+,
SmartCycle+,
TrendCheck+, and
Any previous generation products.

The Gen3 recorders were introduced in 2000 and many components are no longer procurable.

Despite P&WC's best efforts to prolong the life of our Gen3 recorders, effective immediately, P&WC is no longer accepting NEW Gen3 system orders.

Customers may continue to use the currently installed and functioning Gen3 recorders.

P&WC will continue to support repairs of Gen3 recorders as long as spare parts are available and units can be recertified, but P&WC can no longer guarantee spare parts availability. Following troubleshooting with DPHM support team, any unit will first need to be inspected at the PWES Norwood authorized Repair Station before P&WC can confirm if repairs are possible or if serviceable inventory is available for sale.

This Service Information Letter is valid until superseded or cancelled by revision.

ISSUED: 27-Mar-2023 Page 1 of 3 REVISED: 23-May-2024

Pratt & Whitney Canada Corp. SERVICE INFORMATION LETTER

The Data Transmission Unit (DTU) has older technology infrastructure and cannot be upgraded with a 4G/LTE modem from its current 2G or 3G modems.

P&WC continues to invest in the new recorder technology called the Flight-Data Acquisition, Storage and Transmission (FASTTM) system and has developed a FASTTM system to replace 90+% of the active Gen3 recorders in the field. As worldwide cellular carriers gradually shut down their 2G and 3G cellular networks to free up spectrum for newer technologies, a FASTTM system will need to be installed to replace the DTU. At time of publication of this SIL, a FASTTM option is available for the following aircraft and engine model combinations which were previously covered by Gen3 system. Where applicable, the Supplemental Type Certificate (STC) document number available on My P&WC Power, is provided.

Aircraft Model	Engine Model	FAST™ Document
		Number on My P&WC
Air Tractor 402A	PT6A-11AG	3134283
Air Tractor 402B	PT6A-15AG	3134283
Air Tractor 502	PT6A-60AG	3134283
Air Tractor 502B	PT6A-34AG	3134283
Air Tractor 502XP	PT6A-140AG	3134283
Air Tractor 504	PT6A-34AG	3134283
Air Tractor 602	PT6A-60AG	3134283
Air Tractor 602	PT6A-65AG	3134283
Air Tractor 802	PT6A-65AG	3134283
Air Tractor 802	PT6A-67AG	3134283
Air Tractor 802	PT6A-67F	3134283
Beechcraft 1900C	PT6A-65B	3137397
Beechcraft 1900D	PT6A-67D	3137397
Beechcraft King Air 200/B2001	PT6A-42	3076083
Beechcraft King Air 300/350/350i/350ER ¹	PT6A-60A	3076083
Beechcraft King Air B200GT/B2501	PT6A-52	3076083
Beechcraft King Air B300(350)/B300C(350C) ¹	PT6A-67A	3076083
Bell 412 ⁴	PT6T-3B	In Progress
Bell 412SP ⁴	PT6T-3BF	In Progress
Bell 412HP ⁴	PT6T-3BG/3D	In Progress
Bell 412EP ⁴	PT6T-3DF	In Progress
Blackhawk VX Caravan	PT6A-42A	3077264
Blackhawk XP140 Caravan	PT6A-140	3077264
Blackhawk XP61 King Air 200/B200	PT6A-61	3076083
Cessna Caravan 208/B ²	PT6A-114	3077264
Cessna Caravan 208/B ²	PT6A-114A	3077264

This Service Information Letter is valid until superseded or cancelled by revision.

ISSUED: 27-Mar-2023 REVISED: 23-May-2024 Page 2 of 3
P&WC Proprietary Information. Subject to restriction on first page.

Pratt & Whitney Canada Corp. SERVICE INFORMATION LETTER

Aircraft Model	Engine Model	FAST™ Document Number on My P&WC
Dassault Falcon 2000 (Dassault Service Bulletin)	PW308C	F2000EX-477R-13
De Havilland Aircraft Dash 8-300	PW123	3074482
De Havilland Aircraft Dash 8-300	PW123B	3074482
De Havilland Aircraft Dash 8-300	PW123E	3074482
Pilatus PC-12	PT6A-67B	3134286
Pilatus PC-12NG	PT6A-67P	3134286

- Note 1: FAST™ STC is available for aircraft with digital cockpit only (ProLine 21, ProLine 21 Configurable, Fusion, or Garmin G1000)
- Note 2: For Caravan aircraft equipped with the G1000 avionics see information below.
- Note 3: Dassault Service Bulletin. Latest revision applies.
- Note 4: FAST™ STC for the Bell 412 is currently in progress.

For more information on the FAST™ system:

- Refer to our website below or to the FAST™ Introduction Package (P/N 3076072) available on the My P&WC

Power portal.

https://customer.pwc.ca/_layouts/app/#/techpubs/pub-details?PubCode=3076072&Media=Online&Language=En

- Contact P&WC:
 - Sales Team: Pavel Pavlov: pavel.pavlov@prattwhitnev.com
- For technical questions, please contact DPHM Customer Support at: DPHMSupport@pwc.ca

For upgrade pricing and availability for Textron Caravan equipped with G1000 avionics, please contact Textron aftermarket sales.

For upgrade pricing and availability through P&WC, please contact P&W Component Solutions at spares@pwc.ca

Respectfully,

Bjorn Stickling Director

Digital Engine Services

PRATT & WHITNEY CANADA CORP

This Service Information Letter is valid until superseded or cancelled by revision.

ISSUED: 27-Mar-2023 REVISED: 23-May-2024 Page 3 of 3

P&WC Proprietary Information. Subject to restriction on first page.