



## TECHNICAL INFORMATION LETTER

TIL N°        T-109E-23-004  
                  T-109L-23-003  
                  T-109S-23-004  
DATE:        August 03, 2023  
REV.:         /

---

To:            Leonardo Helicopters products  
                  Owners / Operators / Service Centres

**SUBJECT:     Update on Central Fuselage Frame Assy at STA 1815  
                  Inspection and Reinforcement of**

Helicopters Affected:    A109E, A109S, A109LUH/LOH

Dear Customer,

With the present letter Leonardo Helicopters (LH) would like to inform you about revision of the following Alert Service Bulletins (ASBs) that are going to be released on AW109 Series helicopters:

- 109EP-179 Rev. A
- 109EP-173 rev. B
- 109S-109 Rev. A
- 109L-120 rev. A.

The revision of the aforementioned ASBs is aimed at installing the LH and RH side fuselage reinforcements as terminating action.

The EASA Airworthiness Directive (AD) 2022-0153, that is endorsing the first issuance of the abovementioned SB, will be revised accordingly.

Should you need any additional information, please do not hesitate to refer to your usual contact within LH Engineering Support team.

Yours Sincerely,

A handwritten signature in black ink, appearing to read "Marco D'Adamo", written over a horizontal line.

Marco D'Adamo  
Head of Product Support Engineering

---