

TCCA AD CF-2015-16R3

Aeronet Galaxy Aerospace > Modifications > Edit - Mozilla Firefox

https://galaxy.aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&templat

AD/SB ID: 9314

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS Repetitive

Reference/Number: TAIL ROTOR - PITCH LINK SPHERICAL BEARING
ACCELERATED WEAR

Title/Subject: CF-2015-16, REV 3 PARA 1 & 3 (ASB 429-15-16 REV)

Version No:

Reason For Raising:

URL:

Date: 14 05 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
	AD NO. CF-2015-16, REV 3	9314-2246.pdf

AD/SB ID: 9314

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-PEC		-		0	-	-	COMPLIED WITH

Edit Limitation

Cancel Save

Linked To: 9M-PEC

Based On: Select

Warning: 0

Warning Unit: Select

Completed:

Due At: -

Status: COMPLIED WITH

Limitation Notes: PARA 1 AND 3: COMPLIED WITH. REFER SAS JOB NO. 18255-4/7 ON 12/3/2019 @1798.80FH (REPLACE NEW TR PITCH LINK ASSY P/N 429-012-112-113 SN TE1929 TSN:NEW)

Aeronet Galaxy Aerospace > Modifications > Edit - Mozilla Firefox

https://galaxy.aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&templat

AD/SB ID: 9312 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS Repetitive

Reference/Number: TAIL ROTOR - PITCH LINK SPHERICAL BEARING
ACCELERATED WEAR

Title/Subject: AD NO. CF-2015-16, REV 3 PARA 2 (ASB 429-15-16 REV C)

Version No:

Reason For Raising:

URL:

Date: 14 05 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename
	AD NO. CF-2015-16, REV 3	9312-2244.pdf

AD/SB ID: 9312 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-PEC	Airframe Hours	50	Hours	25	1876.00	1926.00	Required

Edit Limitation Cancel Save

Linked To: 9M-PEC

Based On: Airframe Hours

Period: 50

Warning: 25

Warning Unit: Hours

Last Done: 1876.00

Next Due: 1926.00

Limitation Notes:

INITIAL COMPLIED WITHIN 10FH: (REFER ASB 429-15-16 REV B PART I)
 REPETITIVE EVRY 50FH:
 C/O: SAS JOB NO. 18255-4/7 ON 12/3/2019 @1798.80FH (REPLACE NEW TR
 PITCH LINK ASSY P/N 429-012-112-113 SN TE1929 TSN:NEW)
 C/O WS REF: WP-PEC-19-880-004 ON 23/12/2019 @1847:24FH
 C/O WP-PEC-20-799 ON 05/11/2020 AT 1876:00HRS

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: TAIL ROTOR - PITCH LINK SPHERICAL BEARING
ACCELERATED WEAR

Title/Subject: CF-2015-16, REV 3 PARA 4 (ASB 429-15-16 REV C)

Version No:

Reason For Raising:

URL:

Date: 14 05 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
AD NO. CF-2015-16, REVISION 3		9311-2243.pdf

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-PEC	On Condition	-		0	-	-	OPTIONAL

Edit Limitation Cancel Save

Linked To: 9M-PEC

Based On: On Condition

Warning: 0

Warning Unit: Select

Completed:

Due At: -

Status: OPTIONAL

Limitation Notes:
COMPLIANCE: AT CUSTOMER OPTION (REVIEWIED WITH OPERATOR, PENDING PERMISSION BY OPERATOR. REFER TIC-429-21-0034 ON 10 MAY 2021