



## TECHNICAL INFORMATION LETTER

TIL N° T-GEN-21-002  
DATE: April 02, 2021  
REV.: /

---

To: Leonardo Helicopters products  
Owners / Operators / Service Centres

**SUBJECT: Cleaning advices – UV Light Cleaning**

Helicopters Affected: All Leonardo Helicopters products

Dear Customer,

Leonardo Helicopters (LH) is pleased to confirm that the usage of UV Light disinfection system is allowed on LH products for the sanitization of the cabin compartment surfaces only, ensuring that separation wall/curtain is properly installed and closed during the disinfection process.

Please refer to the Supplier user manual and instructions for any warning, caution or best practices related to the effect of the usage of the UV Light disinfection system.

Please consider that UV Light disinfection exposure shall be limited to the passenger Cabin compartment liners, floor and furniture (e.g. seats, stretcher, cabinet, etc..).

Finally, with reference to components that are part of a Supplemental Type Certificate (STC), or related to specific mission equipment (e.g. Electro medical equipment, Keyboards, Mission Console, Displays, etc..) no exposition to UV disinfection light are allowed unless confirmed/approved by the relevant STC Holder / component manufacturer.

Should you need any additional information, please do not hesitate to refer to the point of contact provided with the Customer Support & Training Worldwide Directory, available on Leonardo Customer Portal at this [link](#).

Yours Sincerely,

A handwritten signature in black ink that reads "Gabriele Bordino".

---

Gabriele Bordino  
Head of Product Support Engineering

---