

**CHAPTER 04, ISSUE 023, DATED 09/09/2021**

**Section 04-10 Retirement Lives – General**

**Table 2 Retirement Lives – List of affected parts**

REF	PART	PART NUMBER	RETIREMENT LIFE	APPLICABILITY		REMARKS/ ACTION TO BE TAKEN
				9M-BOE	9M-BOF	
RL073A	Main rotor damper body end assembly (Note 6)	M06-01H065-045	1200	X	X	MR Damper Assy fitted is P/N 8G6220V00151.
RL074	Upper rod end	4F6230V00752	18500	/	/	Aeronet to be updated
RL074A	Upper Rod End	8G6230V00151	18500	X	X	N/A
RL075	Lower rod end and tube assembly	4F6230A01034	18500	/	/	Aeronet to be updated

**Section 04-20 Mandatory Inspections – General**

**Table 2 Mandatory inspections - List of affected parts**

REF.	PART	TASK	INTERVAL	REFERENCE (DMC)	APPLICABILITY		REMARKS/ ACTION TO BE TAKEN
					9M-BOE	9M-BOF	
MI62-06	MR Pitch Link assembly (Note 1)	Detailed inspection for cracks in the elastomer (rod ends)	75	89- A-62-31-01-00B-31AA-A	/	/	For information only
MI62-06A	MR Pitch Link assembly (Note 2)	Detailed inspection for cracks in the elastomer (rod ends)	100	89- A-62-31-01-00B-31AA-A	/	/	Aeronet to be updated

**Note**

1. MI62-06 is applicable to Main rotor pitch link assy P/N 4F6230A00534 only.
2. MI62-06A is applicable to Main rotor pitch link assy P/N 8G6230A01031.