

TIC-A109E-21-0091

AD/SB ID: 9575 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: MODIFICATION/REPLACEMENT OF TURBOSHAFT ENGINE
COMBUSTION CHAMBER LINERS ASSEMBLY

Title/Subject: P&WC S.B. No. 28237R2

Version No:

Reason For Raising:

URL:

Date: -- -- -- --

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	+	*	Title	Filename	*
No Documents currently linked to the inspection					

AD/SB ID: 9575 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
@	9M-BOB	On Condition	-		0	-	-	Category 7	🗑