

TIC-A109E-21-0089

INSPECTION ID: 2368 Close Update Save & Close

General | Config List | Aircraft List | Task List | ATA History | Linked To | BOM | Special Tasks

Inspection Type: Special Inspections

Title/Subject: AF 1600 FH INSPECTION

Reference/Number: MPM 05-50-1, MPM 05-70

Version No:

galaxy.aerospace.aeronet.nz/index.html

INSPECTION ID: 2368 Close Update Save & Close

General | Config List | Aircraft List | Task List | ATA History | Linked To | BOM | Special Tasks

Task#	Job#	Title	Budget/Actual	Average	Priority	
14922 ▶	-	SECTION 05-70 (SERVICING) NOSE AND MAIN LANDING GEAR SHOCK STRUTS	0.00	0.00	1.00	🗑
27489 ▶	-	05-50 16(A) SERVO HYDRAULIC SYSTEM	0.00	0.00	2.00	🗑
17089 ▶	-	05-50 16(B) TAIL ROTOR (90°) GEARBOX	0.00	0.00	3.00	🗑
27490 ▶	-	TAIL GEARBOX - SPECIAL INSPECTION	0.00	0.00	4.00	🗑

Task #: 144190 Created: 29/11/2021 Modified: 29/11/2021 Template ID: 27490 Save to template Close Update

General | Accounts | Production | Time Allocations | Documents | ATA List | History

Task Number: 0 Task ID: 144190

Job: 0 #0 - Search Parent: 0 Search

Start Date: 29/11/2021 Created By: CAMO JBPM

Due Date: 01/12/2021 Modified By: CAMO JBPM

Defects/Title: TAIL GEARBOX - SPECIAL INSPECTION Priority: Low

Status: WIP

Reference/AIW: Category:

Details/Rectification: SPECIAL INSPECTION OF TAIL GEARBOX P/N 109-0440-01- 119/-121/-123 TO BE CARRIED OUT
REFERENCE: TMI109-4 05 REV. A (TMI EXPIRED DATE WILL BE ON AUGUST 9TH, 2022)
REMARKS:

Notes:

Task Authority: DONE BY Required