

TIC-AW139-21-0262

AD/SB ID: 9576 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ATA 24 - AUXILIARY OVERHEAD PANEL AND INTERSEAT CONSOLE MODIFICATIONS

Title/Subject: SB 139-667 NEW ISSUE

AD/SB ID: 9576 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU	Not Applicable	-		0	-	-	Required	
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-JPM	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMA	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMB	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PME	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMF	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-SAAS	Not Applicable	-		0	-	-	Required	
	9M-SBH	Not Applicable	-		0	-	-	Required	
	9M-YPG	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE	