TIC-AW139-21-0290

EASA - AW139 AIRWORTHINESS DIRECTIVES ATA 23 - PRIMUS EPIC HARNESSES SOLDER SPLICES - INSPECTION / REPLACEMENT

EASA AD NO. 2011-0140, NEW ISSUE

AD/SB ID: 35	🔀 Close 😏 Update 🔚 Save & Close			
General Config List Aircraft List Task List Linked To BC	M			
Type : ADS V Repetitive				
Reference/Number: ATA 23 - COMMUNICATIONS - PRIMU HARNESSES SOLDER SPLICES - INSU				
Title/Subject: EASA AD NO 2011-0140, NEW ISSUE				

0		.ist Aircraft List Task List Lin	ked To BOM				🗙 Close 🚱 l		
-	eneral Config L								
0	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	Ē
Y	9M-BFU	Not Applicable	-		0	-	-	NOT APPLICABLE	Ť
2	9M-JPM	Not Applicable	-		0	-	-	NOT APPLICABLE	Ť
2	9M-PMA	Not Applicable	-		0	-	-	NOT APPLICABLE	Ť
2	9M-PMB		-		0	-	-	NOT APPLICABLE	1
2	9M-PMC		-		0	-	-	NOT APPLICABLE	Ť
ł	9M-PMD	Airframe Hours	-	Hours	0	-	-	NOT APPLICABLE	1
2	9M-PME	Not Applicable	-		0	-	-	NOT APPLICABLE	Ť
2	9M-PMF	Not Applicable	-		0	-	-	NOT APPLICABLE	Ť
Y	9M-SAAS	Airframe Hours	-	Hours	0	-	-	NOT APPLICABLE	1
2	9M-SBH	Airframe Hours	-	Hours	0	-	-	NOT APPLICABLE	Ť
2	9M-YPG	Not Applicable	-		0	-	-	NOT APPLICABLE	t
Y	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE	1