

TIC-A109E-22-0026

Type :	SBS <input checked="" type="checkbox"/> Repetitive
Reference/Number:	ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPECTION (EVERY 100FH)
Title/Subject:	SB109EP-173 REV. A PART I (EASA AD 2020-0256)
Version No:	

Linked To:	9M-BOB
Based On:	Airframe Hours
Period:	100
Warning:	50
Warning Unit:	Hours
Last Done:	3661.51
Next Due:	3761.51
Limitation Notes:	LAST COMPLIED @ 3661:30 FH ON 26.11.2021 REFER 9M-BOB-8470  TIC-A109E-22-0026 - PART 1: APPLICABLE AND REPETITIVE, EVERY 100FH. - PART II AND PART III: WITHIN AND NOT LATER THAN THE NEXT 25FH IF THE LENGTH OF CRACK ON THE FWD CAP DOES NOT EXCEED 50 MM AND NO OTHER DAMAGES ARE DETECTED IN THE AFFECTED AREA. - BEFORE THE NEXT FLIGHT IF THE LENGTH OF CRACK ON THE FWD CAP IS GREATER THAN 50 MM AND/OR ANY OTHER CRACK(S) ARE DETECTED.