

TIC-A109E-22-0020

AD/SB ID: 9985 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: TURBOSHAFT ENGINE SEAL, STARTER GENERATOR PAD/FCU
PAD/ACCESSORY PAD-REPLACEMENT OF

Title/Subject: SB NO. 28197, REV. 8 ENGINE NO. 1

Version No:

Reason For Raising:

AD/SB ID: 9986 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: TURBOSHAFT ENGINE SEAL, STARTER GENERATOR PAD/FCU
PAD/ACCESSORY PAD-REPLACEMENT OF

Title/Subject: SB NO. 28197, REV. 8 ENGINE NO. 2

Version No: