

Changes in AMPI ALS, Chapter 4: in Issue 23th

Retirement lives

RL073A	Main rotor damper body end assembly (Note 6)	M006-01H065-045	1200
RL074	Upper rod end	4F6230V00752	18500
RL074A	Upper Rod End	8G6230V00151	18500
RL075	Lower rod end and tube assembly	4F6230A01034	18500

Mandatory inspections

MI62-06	MR Pitch Link assembly (Note 1)	Detailed inspection for cracks in the elastomer (rod ends)	75	89-A-62-31-01-00B-31AA-A
MI62-06A	MR Pitch Link assembly (Note 2)	Detailed inspection for cracks in the elastomer (rod ends)	100	89-A-62-31-01-00B-31AA-A

Certification maintenance requirements

CM71-02	Engine installation	FC of EPAC (engine power assurance check) to verify correct data transmission. Confirm the correct operation of the automatic PAC function by comparing its results with those	2400	Note 10
---------	---------------------	--	------	---------