

# TIC-AW139-22-0219

## PART I

AD/SB ID: 10136 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: ATA 29 - NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION

Title/Subject: SB NO. 139-672 REV/ PART I

AD/SB ID: 10136 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Date (Months)	-	Months	3	-	02/03/2023	TO BE COMPLIED	
	9M-BOC	Airframe Hours	-	Hours	50	0.00	3767.30	TO BE COMPLIED	
	9M-BOD	Date (Months)	-	Months	3	-	02/03/2023	TO BE COMPLIED	
	9M-BOD	Airframe Hours	-	Hours	50	0.00	3813.75	TO BE COMPLIED	

## PART II

AD/SB ID: 10137 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: ATA 29 - NUMBER 4 PUMP LINE INSTALLATION VISUAL INSPECTION AND MODIFICATION

Title/Subject: SB NO. 139-672 REV/ PART II

AD/SB ID: 10137 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Date (Months)	-	Months	3	-	02/10/2023	TO BE COMPLIED	
	9M-BOC	Airframe Hours	-	Hours	50	0.00	4667.30	TO BE COMPLIED	
	9M-BOD	Date (Months)	-	Months	3	-	02/10/2023	TO BE COMPLIED	
	9M-BOD	Airframe Hours	-	Hours	50	0.00	4713.75	TO BE COMPLIED	