

# TIC-AW139-22-0224

AD/SB ID: 10103 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS  Repetitive

Reference/Number: TAIL ROTOR - DAMPER BRACKET - INSPECTION

Title/Subject: EASA AD No.: 2022-0205 (SB 139-724 REV B)

AD/SB ID: 10103 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU	Date (Months)	6	Months	3	-	00/00/0000	Required	
	9M-BFU	Airframe Hours	50	Hours	25	0.00	0.00	Required	
	9M-BOC	Not Applicable	6		3	-	-	Required	
	9M-BOC	Not Applicable	50		25	-	-	Required	
	9M-BOD	Not Applicable	6		3	-	-	Required	
	9M-BOD	Not Applicable	50		25	-	-	Required	