

TIC-A109E-23-0001

ENGINE 1

AD/SB ID: 10181 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type : SBS Repetitive

Reference/Number: PW206C SERVICE BULLETIN TURBOSHAFT ENGINE -
COMPRESSOR TURBINE-DISC RETAINING NUT -
REPLACEMENT OF

Title/Subject: P&WC SB NO. 28406, REV. 2 ENG 1

AD/SB ID: 10181 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOB	Not Applicable	-		0	-	-	NOT APPLICABLE	

ENGINE 2

AD/SB ID: 10182 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type : SBS Repetitive

Reference/Number: PW206C SERVICE BULLETIN TURBOSHAFT ENGINE -
COMPRESSOR TURBINE-DISC RETAINING NUT -
REPLACEMENT OF

Title/Subject: P&WC SB NO. 28406, REV. 2 ENG 2

AD/SB ID: 10182 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOB	Not Applicable	-		0	-	-	NOT APPLICABLE	