

TIC-AW189-23-0079

CHAPTER 4:

NO.	REF	DESCRIPTION	APPLICABILITY	PART NUMBER	REMARKS	ACTION
1.	RL070A	PLANET GEAR	NOT APPLICABLE DUE TO NOT INSTALL IN CURRENT FLEET	8G6323L00251	NONE	NONE
2.	RL077	FITTING ASSY MOORING FWD RHS	NOT APPLICABLE DUE TO NOT INSTALL IN CURRENT FLEET	8G1000A04031	NONE	NONE
3.	CM25-11	CARGO HOOK	APPLICABLE	ALL	ADD OF NOTE 15	INCLUDE IN TASK CARD

CHAPTER 5:

NO.	REF	DESCRIPTION	APPLICABILITY	REMARKS	ACTION
1.	93-03	GENERAL VISUAL INSPECTION OF THE OBSTACLE PROXIMITY LIDAR SYSTEM (OPLS) SENSORS.	NOT APPLICABLE DUE TO NOT INSTALL IN CURRENT FLEET	ADD APPLICABILITY OF GBA AND KBA AND EFFECTIVITY K274.	NONE

2.	93-04	FUNCTIONAL CHECK (LASER ALIGNMENT) OF THE OBSTACLE PROXIMITY LIDAR SYSTEM.	NOT APPLICABLE DUE TO NOT INSTALL IN CURRENT FLEET	ADD OF APPLICABILITY GBA AND KBA AND EFFECTIVITY K274.	NONE
3.	18-07	DETAILED INSPECTION OF CIRCULAR FORCE AVCS INSTALLATION.	NOT APPLICABLE DUE TO SERIAL NUMBER NOT AFFECTED	ADD OF APPLICABILITY KBA AND CHANGES OF EFFECTIVITY K277.	NONE
4.	52-11	DETAILED INSPECTION OF ELECTRICAL FOLDABLE FOOTSTEP MECHANISM.	NOT APPLICABLE DUE TO SERIAL NUMBER NOT AFFECTED	ADD OF APPLICABILITY KBA.	NONE
5.	52-10	DETAILED INSPECTION OF CABIN DOOR HANDLE AND LOCKING MECHANISM.	NOT APPLICABLE DUE TO SERIAL NUMBER NOT AFFECTED	ADD OF APPLICABILITY KBA.	NONE
6.	25-26	DETAILED INSPECTION OF THE CABIN CEILING HOOKS.	9M-BOE AND 9M-BOF	ADD OF EFFECTIVITY KC22.	NONE
7.	18-06	FUNCTIONAL CHECK OF THE ACTIVE VIBRATION CONTROL SYSTEM (AVCS).	NOT APPLICABLE DUE TO NOT INSTALL IN CURRENT FLEET	<ul style="list-style-type: none"> - ADD NOT EXCEED 800FH / 2Y BETWEEN 2 CONSECUTIVE CHECKS FROM THE PAST INTERVAL. - ADD OF APPLICABILITY KBA AND CHANGES OF EFFECTIVITY K277. 	NONE