

TIC-AW139-23-0274

NOT APPLICABLE FOR BOTH AW139 JBPM FLEET

AD/SB ID: 10509 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC		-		0	-	-	NOT APPLICABLE	
	9M-BOD		-		0	-	-	NOT APPLICABLE	

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name...

AD/SB ID: 10509 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: ATA 25 - INSTALLATION OF HOIST PENDANT VARIANT P/N 362591A08211

Title/Subject: SB NO. 139-371 REV. A

Version No:

Reason For Raising:

URL:

Date: 04 08 2023