

TIC-AW139-23-0026

NOT APPLICABLE FOR ALL JBPM AW139 FLEET

AD/SB ID: 10213 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
SM-BOC	Date (Months)	- Days		30	-	01/08/2023	NOT APPLICABLE
SM-BOC	Airframe Hours	- Hours		25	0.00	3690.30	NOT APPLICABLE
SM-BOD	Date (Months)	- Days		30	-	01/08/2023	NOT APPLICABLE
SM-BOD	Airframe Hours	- Hours		25	0.00	3650.06	NOT APPLICABLE

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=...

AD/SB ID: 10213 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: Repetitive

Reference/Number: ATA 95 - INSPECTION OF SEALANT OF BLEED COVERS OF EMERGENCY FLOTATION SYSTEM

Title/Subject: SB NO. 139-733, NEW ISSUE