

TIC-A109E-23-0025

NOT APPLICABLE FOR JBPM A109E FLEET

AD/SB ID: 10520 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB	Not Applicable	-		0	-	-	NOT APPLICABLE

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name...

AD/SB ID: 10520 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ATA 62 - INSPECTION AND REPLACEMENT OF MAIN ROTOR BLADE TIP CAP

Title/Subject: ASB NO. 109EP-181, NEW ISSUE PART I, II & III

Version No: