

TIC-A109E-23-0030

PART I

ADI/SB ID: 10574

General | Config List | Aircraft List | Task List | Linked To | BOM

| Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status |
|----------|----------------|-----------|--------------|---------|-----------|----------|-----------------|
| 9M-BOB | Airframe Hours | 100 Hours | | 20 | 3843.89 | 3943.89 | TO BE COMPLETED |

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=...

ADI/SB ID: 10574

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

ReferenceNumber: ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPECTION, REPAIR AND REINFORCEMENT OF

Title/Subject: ASB NO. 109EP-173, REV B PART I (EASA AD 2022-0153)



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]
 Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre,
 Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
 Tel: +603 7734 7228 | Fax: +603 7734 7528
 www.galaxy.aerospacemy | enquiry@galaxy.aerospacemy

WORKPACK



| | | | | | |
|---|--|--|-----------------------------|--|-----------|
| CLIENT/OWNER: JABATAN BOMBA DAN PENYELAMAT MALAYSIA AIRCRAFT TYPE: A109E REGISTRATION: 9M-BOB BASE/FACILITY: MIAF DATE IN: 30-8-23 OUT: 30-8-23 | SERIAL NO. AIRCRAFT: 11212 #1 ENGINE: PCE-BC0308 #2 ENGINE: PCE-BC0358 | HOURS 3843:53 1068:43 3047:23 | LDG/CYCLE 4450 - - | WORKPACK NO: 9M-BOB-14712 WORK/INSP/DESC: SCHEDULED INSPECTION AERONET JOB NO.: 2023-14712 AJL REF NO.: 000117 SHEET: 1 OF 1 | |
| Reason for raising: SCHEDULED INSPECTION TO BE CARRIED OUT I.A.W. EMM PW206C/PW207C REVISION 46 (05-12-2022). IETP A109E, 33rd Issue: 2022-06-10 UPDATE 001 - 2022-11-16. AMP NO. JBPM/CAMO/AMP/A109E ISSUE 2 REV. 0 | Raised by and date: CAMO; Mohd Hafiz Ismail 22/02/2023 | Other requirements/information: NIL | | | |
| List of scheduled inspection and all work carried out under this workpack including individual reference | | DATE INSPECTION COMPLETED | Master Signature Schedule | | |
| NO. | INSPECTION / WORK | WORKSHEET REF | NAME | SIGNATURE | APP/STAMP |
| 1 | ASB NO 109EP-176 // EASA AD NO. 2021-0067, NEW ISSUE/INSPECTION OF ROTOR BRAKE CONTROL CABLE P/N 109-0506-17-113 | 14712-001 | ADZARAI HASIFF | <i>Handwritten signature</i> | |
| 2 | SB109EP-173 REV. A PART I (EASA AD 2022-0153)/ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPECTION (EVERY 100FH) | 14712-002 | AKMAL Hidayat | <i>Handwritten signature</i> | 8320 |

PART II & III

ADI/SB ID: 10588

General | Config List | Aircraft List | Task List | Linked To | BOM

| Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status |
|----------|----------------|---------|--------------|---------|-----------|----------|-----------------|
| 9M-BOB | Airframe Hours | - Hours | | 10 | 0.00 | 3876.97 | TO BE COMPLETED |

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=...

ADI/SB ID: 10588

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

ReferenceNumber: ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPECTION, REPAIR AND REINFORCEMENT OF

Title/Subject: ASB NO. 109EP-173, REV B PART II & III

PART IV & V

AD/ SB ID: 10589 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

| Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status |
|----------|--------------|--------|--------------|---------|-----------|------------|-----------------|
| 9M-B0B | Date (Years) | - Days | | 90 | - | 31/08/2025 | TO BE COMPLETED |

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aerospac.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=...

AD/ SB ID: 10589 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SSS Repetitive

Reference Number: ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPECTION, REPAIR AND REINFORCEMENT OF

Title/Subject: ASB NO. 109EP-173, REV B PART IV & V