

TIC-A109E-23-0008

PART I

AD/ SB ID: 10294

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9A-80B	Date (Months)	Days		30	18/09/2023		COMPLETED WITH
9A-80B	Airframe Hours	Hours		25	3846.45		COMPLETED WITH

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aeronet.nz/index.html?function=aircraft\_templates&opener\_name=aircraft&mode=edit&template=no&opener\_form\_name=...

AD/ SB ID: 10294

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS  Repetitive

Reference Number: ATA 64 - TAIL ROTOR HOUSING AND SLIDER GROUP DISASSEMBLY AND REASSEMBLY

Title/Subject: ASB 109EP-100 REV/ PART I (AO 2023-0105)

PART II – EVERY 400 FH // 12 M

AD/ SB ID: 10295

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9A-80B	Date (Months)	12 Months		3	18/09/2023	17/09/2024	TO BE COMPLETED
9A-80B	Airframe Hours	400 Hours		50	3846.45	4246.45	TO BE COMPLETED

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aeronet.nz/index.html?function=aircraft\_templates&opener\_name=aircraft&mode=edit&template=no&opener\_form\_name=...

AD/ SB ID: 10295

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS  Repetitive

Reference Number: ATA 64 - TAIL ROTOR HOUSING AND SLIDER GROUP DISASSEMBLY AND REASSEMBLY

Title/Subject: ASB NO. 109EP-100 REV/ PART II

Version No: