

TIC-A109E-23-0023

AD/SB ID: 10521 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB		-		0	-	-	OPEN

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=ed...

AD/SB ID: 10521 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: ATA 25 - REPLACEMENT OF THE HOOK ASSEMBLY P/N HK-117-1 WITH THE NEW HOOK ASSEMBLY P/N HK-121-2 OR WITH THE NEW HOOK ASSEMBLY P/N HK-116-2 (THE BOTH

Title/Subject: SB NO. 109EP-048 REV D