

TIC-AW139-21-0239

ENGINE 1

AD/SB ID: 4193 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: PERMANENT MAGNETIC ALTERNATOR GEARSHAFT AND ROLLER BEARING REPLACEMENT OF

Title/Subject: NO. 1 ENGINE - SB NO. 41110 REVISION 2

Version No:

Reason For Raising: CATEGORY 7

AD/SB ID: 4193 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	On Condition	-		0	-	-	Category 7	
	9M-BOD	On Condition	-		0	-	-	Category 7	
	9M-JPM	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMA	On Condition	-		0	-	-	Category 7	
	9M-PMB	On Condition	-		0	-	-	Category 7	
	9M-PMC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMD		-		0	-	-	Category 7	
	9M-PME		-		0	-	-	Category 7	
	9M-PMF	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YPG	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL	On Condition	-		0	-	-	PARTS IS FULLY USED	

ENGINE 2

AD/SB ID: 9765 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: PERMANENT MAGNETIC ALTERNATOR GEARSHAFT AND ROLLER BEARING REPLACEMENT OF

Title/Subject: NO. 2 ENGINE - SB NO. 41110 REVISION 2

Version No:

Reason For Raising: CATEGORY 7

AD/SB ID: 9765 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	On Condition	-		0	-	-	Category 7	
	9M-BOD	On Condition	-		0	-	-	Category 7	
	9M-JPM	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMA	On Condition	-		0	-	-	Category 7	
	9M-PMB	On Condition	-		0	-	-	Category 7	
	9M-PMC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMD	On Condition	-		0	-	-	Category 7	
	9M-PME	On Condition	-		0	-	-	Category 7	
	9M-PMF	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YPG	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL		-		0	-	-	PARTS IS FULLY USED	