

## TIC-AW139-23-0360

### ENGINE 1

AD/SB ID: 11100 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS- INSPECTION/ REPLACEMENT OF

Title/Subject: PT6C-67C SB NO. 41106 , REV. 1 - ENGINE 1

AD/SB ID: 11100 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE	

### ENGINE 2

AD/SB ID: 11101 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS- INSPECTION/ REPLACEMENT OF

Title/Subject: PT6C-67C SB NO. 41106 , REV. 1 - ENGINE 2

AD/SB ID: 11101 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE	