TIC-AW139-23-0096


9M-BOC

THE TOTAL CONTINUE DISCUSSIVE PROBLEMS (TOTAL CONTINUE CO						
EASB 139-754 REV./ PART I (AD No.: 2023-0071-E) (BNF) ATA 62 - MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	Airframe Hours	0.0 Hours	3776:28	-	-	COMPLIED WITH ₽
EASB 139-754 PART II (AD No.: 2023-0071-E) ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION		-	-	-	-	NOT APPLICABLE ₽
EASB 139-754 PART III (AD No.: 2023-0071-E) ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	Airframe Hours	10.0 Hours	3783:41	-	-	COMPLIED WITH ₽

PART I COMPLIANCE



PART III COMPLIANCE



BEEN REVIEWED, CHECKED FOR COMPLETION
DATE 13/4/23 NAME SIGN & APPROVAL DATE
яям САМ
TED AND ACCOMPLISHED IN ACCORDANCE SIGN & APPROVAL SIGN & APPROVAL

9M-BOD

EASB 139-754 PART III (AD No.: 2023-0071-E ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	Airframe Hours	10.0 Hours	3637:43	-	-	COMPLIED WITH ₽
EASB 139-754 PART II (AD No.: 2023-0071-E)™ ATA 62 MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION			-	-		NOT APPLICABLE ₽
EASB 139-754 REV./ PART I (AD No.: 2023-0071-E) (BNF) ATA 62 - MAIN ROTOR (MR) PITCH LINK UPPER ROD END ASSY INSPECTION	Airframe Hours	0.0 Hours	-	-		NOT APPLICABLE ₽

PART III COMPLIANCE

