

# TIC-AW189-23-0136

AD/ISB ID: 11262 Close Update Show & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: **SES** Repetitive

Reference Number: ATA 64 - TAIL ROTOR DAMPER REPLACEMENT

Title/Subject: EASB NO. 189-388 NEW ISSUE

Version No:

Reason For Rating:

URL:

Date: 22 12 2023

AD/ISB ID: 11262 Close Update Show & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
SM-BDE	Not Applicable	-		0	-	-	NOT APPLICABLE
SM-BDF	Not Applicable	-		0	-	-	NOT APPLICABLE