

TIC-AW189-23-0049

“NOT TO BE COMPLIED” STATUS NOT AVAILABLE. UPDATE THE LATEST STATUS AT REMARKS ONLY.

AD/SB ID: 10316 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: ATA 31 - NR1 AZIMUTH CONNECTIONS RETROMOD

Title/Subject: SB NO. 189-377, NEW ISSUE

AD/SB ID: 10316 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOE	On Condition	-		0	-	-	OPTIONAL	
	9M-BOF	On Condition	-		0	-	-	OPTIONAL	

Edit Limitation Cancel Save

Linked To: 9M-BOE

Based On: On Condition

Warning: 0

Warning Unit: Select

Completed:

Due At: -

Status: OPTIONAL

Limitation Notes:
REFER TIC-AW189-23-0049
APPLICABLE TO THIS AIRCRAFT TYPE
OPERATOR ACTION: NOT TO BE COMPLIED WITH. REFER ADSB/JBPM/23-004 DATED 04-06-2023

Edit Limitation Cancel Save

Linked To: 9M-BOF

Based On: On Condition

Warning: 0

Warning Unit: Select

Completed:

Due At: -

Status: OPTIONAL

Limitation Notes:
REFER TIC-AW189-23-0049
APPLICABLE TO THIS AIRCRAFT TYPE
COMPLIANCE: UPON CUSTOMER'S OPTION
OPERATOR ACTION: NOT TO BE COMPLIED WITH. REFER ADSB/JNPM/23-004 DATED 14-06-2023