

TIC-AW139-22-0246

Edit Limitation (A/C: 9M-YTL)

Edit Limitation EASA AD 2022-0209-E (SB 139-731 REV./ PART 2) - ATA 91 HARN...

Based On: Airframe Hours

Warning: 25

Warning Unit: Hours

Completed: 348.67

Due At: 398.67

Status: COMPLIED WITH

Limitation Notes: REFER TIC-AW139-22-0246 APPLICABLE DUE TO AIRCRAFT S/N AFFECTED. LAST DONE - WP NO. 9M-YTL-13062 AT 348:40FH ON 12-OCT-22 (AJL 1569)

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=e...

AD/SB ID: 10134

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 91 HARNES INSTALLATION FORWARD ROOF AREA INSPECTION

Title/Subject: EASA AD 2022-0209-E (SB 139-731 REV./ PART 2)

Version No:

Edit Limitation (A/C: 9M-YTL)

Edit Limitation EASA AD 2022-0209-E (SB 139-731 REV./ PART 1) - ATA 91 HARN...

Based On: Airframe Hours

Warning: 5

Warning Unit: Hours

Completed: 348.67

Due At: 358.67

Status: COMPLIED WITH

Limitation Notes: TIC-AW139-22-0246 APPLICABLE DUE TO AIRCRAFT S/N AFFECTED. LAST DONE - WP NO. 9M-YTL-13059 AT 348:40FH ON 12-OCT-22 (AJL 1569)

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=e...

AD/SB ID: 10133

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 91 HARNES INSTALLATION FORWARD ROOF AREA INSPECTION

Title/Subject: EASA AD 2022-0209-E (SB 139-731 REV./ PART 1)

Version No: