

TIC-AW139-23-0361

Edit Limitation (A/C: 9M-YTL)

Edit Limitation NO. 1 ENGINE - SB NO. 41106 , REV. 1-TURBOSHAFT ENGINE T1 S...

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: REFER TIC-AW139-23-0361
NOT APPLICABLE TO ENGINE SN AND T1 SENSOR SN AND T1 SENSOR WAS NOT ORDERED BETWEEN JAN 2020 - DEC 2022

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=e...

AD/SB ID: 11139

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS-INSPECTION/ REPLACEMENT OF

Title/Subject: NO. 1 ENGINE - SB NO. 41106 , REV. 1

Status
NOT APPLICABLE
NOT APPLICABLE
NOT APPLICABLE
NOT APPLICABLE
Category 6
Category 6
Category 7
Category 7

Edit Limitation (A/C: 9M-YTL)

Edit Limitation NO.2 ENGINE - SB NO. 41106 , REV. 1-TURBOSHAFT ENGINE T1 SE...

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: REFER TIC-AW139-23-0361
NOT APPLICABLE TO ENGINE SN AND T1 SENSOR SN AND T1 SENSOR WAS NOT ORDERED BETWEEN JAN 2020 - DEC 2022

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=e...

AD/SB ID: 11140

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: TURBOSHAFT ENGINE T1 SENSOR WIRING HARNESS-INSPECTION/ REPLACEMENT OF

Title/Subject: NO.2 ENGINE - SB NO. 41106 , REV. 1

Status
NOT APPLICABLE
NOT APPLICABLE
NOT APPLICABLE
NOT APPLICABLE
Category 6
Category 6
Category 7
Category 7