

**Edit Limitation** Cancel Save

Linked To: 9M-BGH

Based On: Airframe Hours

Warning: 5

Warning Unit: Hours

Completed:

Due At: -

Status: COMPLIED WITH

Limitation Notes:  
 REFER TIC-AW139-22-0328  
 APPLICABLE DUE TO AIRCRAFT S/N AFFECTED.WITHIN 10 FH AFTER THE EFFECTIVE DATE OF THIS AD [12 OCTOBER 2022]  
 PART I: COMPLIED AT 300:40FH ON 15-NOV-22 (WP 2022/31763/004-18)

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft\_templates&opener\_name=aircraft&mode=edit&template=no&opener\_form\_name=e...

AD/SB ID: 10133 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS  Repetitive

Reference/Number: ATA 91 HARNESS INSTALLATION FORWARD ROOF AREA INSPECTION

Title/Subject: EASA AD 2022-0209-E (SB 139-731 REV/ PART 1)

Version No:

**Edit Limitation** Cancel Save

Linked To: 9M-BGH

Based On: Airframe Hours

Warning: 25

Warning Unit: Hours

Completed:

Due At: -

Status: COMPLIED WITH

Limitation Notes:  
 REFER TIC-AW139-22-0328  
 PART I: COMPLIED AT 300:40FH ON 31-NOV-22 (WP 2022/31763/004-18)  
 PART II: COMPLIED AT 300:40FH ON 31-NOV-22 (WP 2022/31763/004-19)

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft\_templates&opener\_name=aircraft&mode=edit&template=no&opener\_form\_name=e...

SB ID: 10134 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS  Repetitive

Reference/Number: ATA 91 HARNESS INSTALLATION FORWARD ROOF AREA INSPECTION

Title/Subject: EASA AD 2022-0209-E (SB 139-731 REV/ PART 2)

Version No: