

# TIC-AW139-24-0112

ADI/SB ID: 11651 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference Number: ATA 95 - EMERGENCY FLOATATION CONTROL PANEL REPLACEMENT

Title/Subject: ASB NO. 139-777 NEW ISSUE

Version No:

Reason For Raising:

URL:

Date: 23 05 2024

Tolerance: % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:  Title: 11651-3633.pdf Filename:

ADI/SB ID: 11651 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOC	Not Applicable	-	-	0	-	-	NOT APPLICABLE
9M-BOD	Not Applicable	-	-	0	-	-	NOT APPLICABLE
9M-PMA	Not Applicable	-	-	0	-	-	NOT APPLICABLE
9M-PMB	Not Applicable	-	-	0	-	-	NOT APPLICABLE
9M-PMD	Not Applicable	-	-	0	-	-	NOT APPLICABLE
9M-PME	Not Applicable	-	-	0	-	-	NOT APPLICABLE
9M-PMF	Not Applicable	-	-	0	-	-	NOT APPLICABLE