

TIC-AW139-22-0180

AD/SB ID: 10043 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT

Title/Subject: AD 2022-0182-E PARA (7), (SBEA 139-725 REV.A PART IV)

Version No:

Reason For Raising:

AD/SB ID: 10043 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU	Airframe Hours	-	Hours	0	-	-	Required	
	9M-BGH	Airframe Hours	-	Hours	0	-	-	NOT APPLICABLE	
	9M-BOC	Airframe Hours	-	Hours	50	3356.68 ↗	-	COMPLIED WITH	
	9M-BOD	Airframe Hours	-	Hours	0	3513.75 ↗	-	COMPLIED WITH	