

TIC-AS350-24-0124

The image shows two overlapping windows from the Aeronet software. The top window is titled 'Edit Limitation (A/C: 9M-LKE)'. It contains the following fields:

- Based On:** Not Applicable
- Warning:** 0
- Warning Unit:** Select
- Completed:** -
- Due At:** 0.00
- Status:** NOT APPLICABLE
- Limitation Notes:** TIC-AS350-24-0124
NOT APPLICABLE DUE TO MOD 075601 EMBODIED ON AIRCRAFT.
COMPLIANCE: NOT APPLICABLE FOR COMPLIANCE.

The bottom window is a Microsoft Edge browser displaying the URL: https://galxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&to.... The page title is 'AD/SB ID: 11710'. The main content area shows the 'Edit - Personal 3' form with the following details:

- Type:** ADS (checked), Repetitive (unchecked)
- Reference/Number:** ATA 64 CANCELLED: TAIL ROTOR LAMINATED HALF-BEARINGS INSPECTION / REPLACEMENT
- Title/Subject:** EASA AD NO. 2012-0257-CN, NEW ISSUE
- Version No.:** (empty)
- Reason For Raising:** (empty)
- URL:** (empty)
- Date:** (calendar icon)
- Tolerance:** 0 % (Whole numbers only)
- Creep Type:** Creep on Completion Unit
- Document:** + * (icon)
- Title:** (input field)
- Filename:** (input field)

Figure 1: 9M-LKE AERONET UPDATED