## TIC-AW139-24-0141

			Edit Limitation (A/C:	NN-8AA 8)		×	
			Edit Limitation S	B NO. 139-616 NEW ISSUE-LEONARDO HELICOPTERS - AW139 SERVI	Cancel		
			Based On:	Not Applicable			
			Warning:	0			
			Warning Unit:	Select V			
			Completed:	· ·			
			Due At:	0.00			
			Status:				
/			-	TIC-AW139-24-0141			
				APPLICABILITY: NOT APPLICABLE DUE TO NOT AFFECTED BY SERIAL NUMBER COMPONENT. AIRCRAFT FITTED WITH ASSEMBLY PART NUMBER 3G5350400136 WITH SERIAL NUMBER PZL262C	TAIL BOC	Based	Dn
			Limitation Notes:	COMPLIANCE:		te (Mor	ths)*
				PART I: NOT APPLICABLE. SERIAL NUMBER TAIL BOOM ASSEMBLY NOT AFFECTED PART II: NOT APPLICABLE. COMPONENT PART NUMBER NOT AFFECTED		irame H	
				PART III: NOT APPLICABLE. COMPONENT PART NUMBER NOT AFFECTED		🔻 irame H	
	Aeronet	Galaxy Aer	ospace > Modific	ations >Edit - Personal 3 - Microsoft Edge			×
	۰						A
https://galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=nor							
ADISB ID: 11772							ave & Close
	General C	Config List Ai	rcraft List Task/Cheol	List Linked To BOM			
		Type : SBS	▼ C Repetitive				
π	Reference/N	NUMMBER: LEONARDO HELICOPTERS - AW139 SERVICE BULLETIN ATA 53 - LOWER LH TAIL LONGERON INSPECTION AND REPAIR					
	Title/S	ubject: SB N	IO. 139-816 NEW ISSU	E			
	Versi	ion No:					
TE	Reason For R	taising:					
		URL:					
		Date: 🗕 🔪	/ - • •				
	Tole	erance:	0 % (Whole numbe	rs only)			
			p on Completion Unit	V			
	Doc	ument: + ¢	•	Title Filename			0
				No Documents currently linked to the inspection			

Figure 1: 9M-SAAS AERONET HAS BEEN UPDATED