(A/C: 9M-PTA)	
tion MTL-53-04, R3-FUSELAGE - FORWARD FUSELAGE FA	STENER INSPECTI Cancel Sa
Based On:	Not Applicable V
Warning:	0
Warning Unit:	Select 🗸
Completed:	_
Due At:	0.00
Status:	NOT APPLICABLE V
Limitation Notes:	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER FL-587 NOT AFFECTED. REFER TIC-B300-24-0012 DATED 19.03.2024
(A/C: 9M-PTB)	
tion MTL-53-04, R3-FUSELAGE - FORWARD FUSELAGE FA	STENER INSPECTI ⊠Cancel 🔚 Sax
Based On:	Not Applicable V
Warning:	0
Warning Unit:	Select 🗸
Completed:	_
Due At:	0.00
Status:	NOT APPLICABLE V
Limitation Notes:	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER FL-593 NOT AFFECTED. REFER TIC-B300-24-0012 DATED 19.03.2024
(A/C: 9M-PTC)	
tion MTL-53-04, R3-FUSELAGE - FORWARD FUSELAGE FA	STENER IN SPECTI Cancel Sav
Based On:	Not Applicable V
Warning:	0
Warning Unit:	Select V
Completed:	
Due At:	0.00
Status:	NOT APPLICABLE V
Limitation Notes:	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER FL-598 NOT AFFECTED. REFER TIC-B300-24-0012 DATED 19.03.2024
(A/C: 9M-PTD)	
ion MTL-53-04, R3-FUSELAGE - FORWARD FUSELAGE FA	ATTAINED WARRANT
	STENER INSPECTI IXICancel List Sal
Based On:	
	Not Applicable
Based On: Warning:	Not Applicable 0
Based On: Warning: Warning Unit:	Not Applicable 0
Based On: Warning: Warning Unit: Completed:	Not Applicable 0 Select - 0.00
Based On: Warning: Warning Unit: Completed: Due At:	Not Applicable 0 Select - 0.00

