n (A/C: 9M-PTA)	
ation MTL-53-05, REV. 3-FUSELAGE - FILLER SHIM OR FAS	TENER INSTAL
Based On:	Not Applicable V
Warning:	0
Warning Unit:	Select V
Completed:	_
Due At:	0.00
Status:	NOT APPLICABLE V
Limitation Notes:	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. REFER TIC-B300-23-0079 DATED ON 01.12.2023.
(A/C: 9M-PTB)	
tion MTL-53-05, REV. 3-FUSELAGE - FILLER SHIM OR FAST	TENER INSTAL ☐ Cancel
Based On:	Not Applicable V
Warning:	0
Warning Unit:	Select v
Completed:	_
Due At:	0.00
Status:	NOT APPLICABLE 🗸
Limitation Notes:	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. REFER TIC-B300-23-0079 DATED ON 01.12.2023.
(A/C: 9M-PTC)	
tion MTL-53-05, REV. 3-FUSELAGE - FILLER SHIM OR FAS	TENER INSTAL
Based On:	Not Applicable
Warning:	0
Warning Unit:	Select V
Completed:	
Due At:	0.00
Status:	NOT APPLICABLE 🗸
Limitation Notes:	NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER NOT AFFECTED. REFER TIC-B300-23-0079 DATED ON 01.12.2023.

