

(A/C: 9M-PTA)

tion MTL-55-02 REV. 1-STABILIZERS - HORIZONTAL FASTENER REPLACEM...

Based On: Not Applicable ▼

Warning: 0

Warning Unit: Select ▼

Completed: -

Due At: 0.00

Status: FOR INFO ONLY ▼

Limitation Notes:

NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER.
REFER TIC-B300-23-0074 DATED 16.11.2023.

(A/C: 9M-PTB)

tion MTL-55-02 REV. 1-STABILIZERS - HORIZONTAL FASTENER REPLACEM...

Based On: Not Applicable ▼

Warning: 0

Warning Unit: Select ▼

Completed: -

Due At: 0.00

Status: FOR INFO ONLY ▼

Limitation Notes:

NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER.
REFER TIC-B300-23-0074 DATED 16.11.2023.

(A/C: 9M-PTC)

tion MTL-55-02 REV. 1-STABILIZERS - HORIZONTAL FASTENER REPLACEM...

Based On: Not Applicable ▼

Warning: 0

Warning Unit: Select ▼

Completed: -

Due At: 0.00

Status: FOR INFO ONLY ▼

Limitation Notes:

NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER.
REFER TIC-B300-23-0074 DATED 16.11.2023.

(A/C: 9M-PTD)

tion MTL-55-02 REV. 1-STABILIZERS - HORIZONTAL FASTENER REPLACEM...

Based On: Not Applicable ▼

Warning: 0

Warning Unit: Select ▼

Completed: -

Due At: 0.00

Status: FOR INFO ONLY ▼

Limitation Notes:

NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER.
REFER TIC-B300-23-0074 DATED 16.11.2023.

(A/C: 9M-PTE)

tion MTL-55-02 REV. 1-STABILIZERS - HORIZONTAL FASTENER REPLACEM...

Based On: Not Applicable ▼

Warning: 0

Warning Unit: Select ▼

Completed: -

Due At: 0.00

Status: NOT APPLICABLE ▼

Limitation Notes:

NOT APPLICABLE TO AIRCRAFT SERIAL NUMBER.
REFER TIC-B300-23-0074 DATED 16.11.2023.