

TIC-EC120B-24-0004

The image shows a screenshot of a web application interface. At the top, a dialog box titled "Edit Limitation (A/C: 9M-GAS)" is open. It contains the following fields:

- Based On: Select
- Warning: 0
- Warning Unit: Select
- Completed: -
- Due At: 0.00
- Status: FOR INFO ONLY
- Limitation Notes: TIC-EC120B-24-0004  
COMPLIED WITH R1, R2 HAS NO EFFECT ON R1, REFER 9M-GAS-8729

Below the dialog box, a browser window shows the URL: [https://galaxy aerospace.aeronet.nz/index.html?function=aircraft\\_templates&opener\\_name=aircraft&mode=edit&template=no&o...](https://galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&o...)

The main application window displays the "AD/SB ID: 11238" and has tabs for "General", "Config List", "Aircraft List", "Task/Check List", "Linked To", and "BOM". The "General" tab is active, showing the following fields:

- Type: SBS  Repetitive
- Reference/Number: PROTECTIVE MEASURE - REAR FUSELAGE CORROSION ON THE TAIL BOOM
- Title/Subject: ASB NO. EC120-53A017 , REV 2
- Version No:
- Reason For Raising:
- URL:
- Date: -- -- -- --
- Tolerance: 0% (Whole numbers only)
- Creep Type: Creep on Completion Unit