

TIC-EC120B-24-0003

The image shows a screenshot of a web application interface. At the top, there is a dialog box titled "Edit Limitation (A/C: 9M-GAS)". The dialog box contains the following fields:

- Based On: Select
- Warning: 0
- Warning Unit: Select
- Completed: -
- Due At: 0.00
- Status: NOT APPLICABLE
- Limitation Notes: TIC-EC120B-24-0003
NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH VOR. REFER ECM WO# 2014 449 00

Below the dialog box, a browser window is open to "Aeronet Galaxy Aerospace > Modifications > Edit - Personal 3 - Microsoft Edge". The browser address bar shows the URL: https://galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_...

The browser window displays a page titled "AD/SB ID: 11246" with the following tabs: General, Config List, Aircraft List, Task/Check List, Linked To, BOM. The "General" tab is active, showing the following details:

- Type: SBS Repetitive
- Reference/Number: PROTECTIVE MEASURE -FUSELAGE - TAIL BOOM CORROSION ON THE TAIL BOOM
- Title/Subject: ASB NO. EC120-53A015 , REV 2
- Version No:
- Reason For Raising:
- URL:
- Date: -- -- --
- Tolerance: 0% (Whole numbers only)
- Creep Type: Creep on Completion Unit