## TIC-EC120B-23-0051

	Edit Limitation (A/C:	SM-GA S)		×	
ance Oper	Edit Limitation	B NO. 319 26 4099 , NEW ISSUE-SAFRAN ENGINES - ARRIUS 2F S	Cancel	Ser 🗍	
	Based On:	Airframe Hours			
	Warning:	100			
	Warning Unit:	Hours V			
	Completed:	0.00			
	Due At:	4837.90			
Flight History	Status:	TO BE COMPLIED			
×		TIC-EC120B-23-0051			
		APPLICABILITY: APPLICABLE TO ENGINE TYPE		- 1	
	Limitation Notes:	COMPLIANCE: TO COMPLY WITH WHEN REPLACING FIRE DETECTOR DUE AS PER ENGINE GAS GENERATOR MODULE 02 OVH AT 4837:54FH		- 1	Warnii
				- 1	3.0 Mor
Aeronet	Galaxy Aerospac	e > Modifications >Edit - Personal 3 - Microsoft Edge	_	0	×
<sup>₩A:</sup> 🗗 htt					ξ A <sup>%</sup>
		space.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&templa			· .
AD/SB ID: 117	79	×c	lose 😏Upd	ate 🗐	Save & Close
General Config List Aircraft List Task/Check List Linked To BOM					
	Type: SBS 🗸	Repetitive			
Reference/	Reference/Number: SAFRAN ENGINES - ARRIUS 2F SERVICE BULLETIN FIRE DETECTION - 🗔 🤤				
-	FIRE D	ETECTION ASSEMBLY. MODIFICATION TF 99			
Title	Subject: SB NO 3	19 28 4099 , NEW ISSUE			
	sion No:				
Reason For					
E BL	Ū.				
IUE	URL:				
ET	Date: 🗸				
LIDII To	lerance:	Whole numbers only)			
IN C	ep Type: Creep on	Completion Unit			

Figure 1: 9M-GAS AERONET HAS BEEN UPDATED