

Document Reference

Document ID	PSE/TQ/2023/122712	Contact	MUHAMMAD IHSAN MASRI
Your Code Reference		Subject	MAIN ROTOR INSTALLATION PART NUMBER
Topic	TECHNICAL	Subtopic	SUPPORT
Issue	TECHNICAL PUBLICATION CLARIFICATION	Team Legal Entity	Italy

Contact Details

Customer Description	GALAXY HELICOPTERS(M) SDN BHD	Customer ID	0006005700
Email	ihsan@galaxyaerospace.my		

Contacts List

First Name	Last Name	Email	User Type
TECHNICAL	SERVICES	tech.services@galaxyaerospace.my	Engineering Officer

Customer Service

Priority	Routine	Creation On (UTC)	31/08/2023
Resolve By (UTC)	15/09/2023	Leonardo Closure Date (UTC)	01/09/2023
Additional Note			

Helicopter Data

ATA Code	62	Description	MAIN ROTOR(S)
Helicopter S/N	NC0031913	Aircraft Tail Number	9M-PMF
Helicopter Line	AW139	Helicopter Model	AW139
Repair Instruction Query	False		

Part Number	Component S/N	Component F/H	On (Date)(UTC)
{product:productnumber} - {product:name}			

Flight Hours	FH Last Update	Create date
973,15	09/08/2023	09/08/2023

Ticket Description

Dear LH,

With reference to IPD 39-A-62-21-00-010-941A-A, applicable P/Ns for Main Rotor Installation without FIPS for AW139 with Model Version Enhanced Plus are 3G6200A00114 and 3G6200A00115. Difference between the P/N and the latter is the UOCA used. Can you clarify which P/N is fitted to aircraft MSN 31913.

Regards,

Ihsan

History Log

Closing Note

Dear Ihsan,

With reference to your request, please be informed that the Main Rotor installation 3G6200A00115 is the latest configuration which already embody the part required from SB139-757. Therefore, for your H/C we believe it has not complied SB139-757 and hence, it should have the installation -114.

Regards,
Dhana