

Annex 1 - AIRWORTHINESS DIRECTIVES STATUS LIST

Helicopter type: AW139
S/N: 31913

| | |
|--------------------|------------|
| Last Check: | |
| <u>TCCA:</u> | CF-2020-01 |
| <u>EASA:</u> | 2020-0131 |
| <u>ENAC:</u> | 2019-003 |
| <u>FAA:</u> | 2020-06-11 |

Date: 16/06/2020
Signature: Zantomio

| AUTHORITY | APPLICABLE AD | ISSUE DATE | TITLE | STATUS | NOTES |
|-----------|---------------------------|------------|--|--------|---|
| EASA | 2019-0235 | 20/09/2019 | ATA 25 – Equipment / Furnishings – Emergency Locator Transmitter – Inspection / Modification / Replacement | N/A | DIFFERENT P/N INSTALLED |
| EASA | 2019-0311 | 19/12/2019 | ATA 25, 95 – Equipment / Furnishings, Emergency Flotation System – Inflation Hoses – Inspection | N.A. | DIFFERENT P/N INSTALLED |
| EASA | 2020-0011 | 29/01/2020 | ATA 63 - Main Gear Box - Bearing Lock Nut - Replacement | N.C.W. | AFTER REACHED 28000 LANDINGS ACCUMULATED, TO BE APPLIED WITHIN 2000 LANDINGS OR NEXT OVERHAUL. SEE BT 139-567 |
| EASA | 2020-0013 | 29/01/2020 | ATA 26 - Fire Protection - Hand-held Fire Extinguishers - Replacement | N.A. | INSTALLED COMPONENT NOT AFFECTED |
| EASA | 2020-0131 | 05/06/2020 | Equipment / Furnishings – Hoist Cable Cutter Frame – Modification | C.W. | IMPLEMENTED |
| ENAC | 2006-095 | 30/03/2006 | MEGGITT SMOKE DETECTORS MODEL 602 REPLACEMENT | N.A. | NOT APPLICABLE: INSTALLED DIFFERENT P/N (REF. HELICOPTER LOGBOOK) |
| ENAC | 2006-458 | 04/12/2006 | EXHAUST - TAILPIPE ASSEMBLY - INSPECTION/REPAIR/REPLACEMENT | N.A. | NOT APPLICABLE: INSTALLED A DIFFERENT P/N (REF. HELICOPTER LOGBOOK) |
| ENAC | 2007-225 | 15/06/2007 | EQUIPMENT - HONEYWELL COMM AND MOD S XPDR XPDR STAND-BY MODE | N.A. | NOT APPLICABLE: MODE S TRANSPONDER NEW P/N INSTALLED (REF. HELICOPTER LOGBOOK) |
| ENAC | 2007-227 | 18/06/2007 | AGUSTA HELICOPTERS AB139/AW139 ENGINE FIRE EXTINGUISHER BOTTLE P/N 3G2620V00131. | N.A. | NOT APPLICABLE: MODIFICATION ALREADY INCORPORATED ON THE HELICOPTER. |
| ENAC | 2008-199 | 09/06/2008 | WINDOWS – COCKPIT DOORS WINDOWS REPLACEMENT | N.A. | NOT APPLICABLE PER HELICOPTER S/N: INSTALLED DIFFERENT WINDOW P/N (REF. HELICOPTER LOGBOOK) |
| ENAC | 2008-295 | 06/08/2008 | FUSELAGE – WIRE STRIKE PROTECTION SYSTEM (WSPS) TOP CABLE CUTTER - REWORK/REPLACEMENT | N.A. | KIT NOT INSTALLED |
| ENAC | 2009-80 | 10/03/2009 | ELECTRICAL POWER – GENERATOR CONTROL UNIT (GCU) - REPLACEMENT | N.A. | NOT APPLICABLE: INSTALLED GCU P/N 1152550-4. |
| ENAC | 2009-382 | 25/11/2009 | FIRE PROTECTION - PORTABLE FIRE EXTINGUISHER - IDENTIFICATION/REPLACEMENT | N.A. | COMPONENT NOT AFFECTED |

C.W. = Compliant With
N.C.W. = Not Complied With
N.A. = Not Applicable