

CHAPTER 71 - LIST OF EFFECTIVE PAGES

<u>Chapter</u> <u>Section</u> <u>Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71		LIST OF EFFECTIVE PAGES	* 1 - 8	June 15/2024
71		TABLE OF CONTENTS	1 - 8	Dec. 30/2023
71-00-06	INT-802-A01	TROUBLESHOOTING - INTRODUCTION	1 - 12	Dec. 30/2022
71-00-06	RPU-801-A01	LIST OF FAILURES FOUND DURING OPERATION - LIST OF FAILURES OBSERVED DURING ENGINE OPERATION	101 - 104	Dec. 30/2022
71-00-06	RPM-802-A01	LIST OF FAILURES OBSERVED DURING MAINTENANCE - LIST OF FAILURES OBSERVED DURING MAINTENANCE	101 - 102	June 15/2022
71-00-06	RPA-803-A01	LIST OF FAILURES CODES - LIST OF FAILURE CODES	* 101 - 112	June 15/2024
71-00-06	811-801-A01	FUEL FILTER PRECLOGGING IS ON OR FLASHING - TROUBLESHOOTING	101 - 104	June 15/2020
71-00-06	811-802-A01	LOW FUEL PRESSURE LIGHT REMAINS OFF - TROUBLESHOOTING	101 - 106	Dec. 30/2022
71-00-06	811-803-A01	LOW OIL PRESSURE LIGHT REMAINS OFF - TROUBLESHOOTING	101 - 106	Dec. 30/2022
71-00-06	811-804-A01	RED GOV AT POWER ON - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	811-822-A01	STEADY AMBER AT POWER ON - TROUBLESHOOTING	101 - 102	Dec. 30/2022
71-00-06	812-802-A01	LIGHT FAILS TO TURN OFF - LOW FUEL PRESSURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	812-804-A01	ENGINE PARAMETER OUT OF LIMIT - T4.5 OVERTEMPERATURE DURING START - TROUBLESHOOTING	101 - 106	Dec. 30/2020
71-00-06	812-805-A01	ABORTED START - GAS GENERATOR NOT DRIVEN - TROUBLESHOOTING	101 - 108	Dec. 30/2021
71-00-06	812-806-A01	LOW OIL PRESSURE LIGHT FAILS TO TURN OFF - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	812-807-A01	ABORTED START - NO IGNITION - TROUBLESHOOTING	101 - 112	June 15/2022

* Page modified following update No. 28

SAFRAN HELICOPTER ENGINES

ARRIEL 2 D

MAINTENANCE MANUAL

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	812-807-B01	ABORTED START - NO IGNITION - TROUBLESHOOTING	101 - 112	June 15/2022
71-00-06	812-808-A01	ABORTED START - SLOW START OR STAGNATION - TROUBLESHOOTING	101 - 108	June 15/2022
71-00-06	812-808-B01	ABORTED START - SLOW START OR STAGNATION - TROUBLESHOOTING	101 - 108	June 15/2022
71-00-06	812-810-A01	ABORTED START - FLAME OUT - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	812-811-A01	ABORTED START - FIRST START ABORTED - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	812-812-A01	ABORTED START - FLAMES AT THE EXHAUST PIPE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	812-816-A01	HELICOPTER ROTOR MOVEMENT THAT OCCURS AFTER THE USUAL TIME DURING ENGINE START - TROUBLESHOOTING	101 - 104	Dec. 30/2019
71-00-06	813-801-A01	SURGE - TROUBLESHOOTING	101 - 106	June 15/2021
71-00-06	814-801-A01	ENG CHIP ON - INDICATOR LIGHT OF THE ELECTRICAL MAGNETIC PLUG ON - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	814-802-A01	LIGHT TURN ON - FUEL FILTER PRECLOGGING - TROUBLESHOOTING	101 - 104	June 15/2022
71-00-06	814-802-B01	LIGHT TURN ON - FUEL FILTER PRECLOGGING - TROUBLESHOOTING	101 - 104	June 15/2022
71-00-06	814-803-A01	LOW FUEL PRESSURE: LIGHT TURNS ON AND/OR MAINTENANCE FLAG - TROUBLESHOOTING	101 - 102	June 15/2022
71-00-06	814-803-B01	LOW FUEL PRESSURE: LIGHT TURNS ON AND/OR MAINTENANCE FLAG - TROUBLESHOOTING	101 - 102	June 15/2022
71-00-06	814-805-A01	MAINT XXX4 - ENGINE PARAMETER OUT OF LIMIT - TORQUE LIMITATIONS EXCEEDED - TROUBLESHOOTING	101 - 102	Dec. 30/2020
71-00-06	814-806-A01	MAINT XXX2 - ENGINE PARAMETER OUT OF LIMIT - N1 LIMITATIONS EXCEEDED - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	814-807-A01	MAINT XXX1 - ENGINE PARAMETER OUT OF LIMIT - N2 LIMITATIONS EXCEEDED - TROUBLESHOOTING	101 - 102	June 15/2020

* Page modified following update No. 28

List of Effective Pages

Page 2

71

June 15/2024

SAFRAN HELICOPTER ENGINES

ARRIEL 2 D

MAINTENANCE MANUAL

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	814-808-A01	UNUSUAL OIL PRESSURE INSTABILITY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	814-809-A01	LIGHT TURN ON - LOW OIL PRESSURE - TROUBLESHOOTING	101 - 104	Dec. 30/2023
71-00-06	814-810-A01	MAINT X2XX - ENGINE PARAMETER OUT OF LIMIT - OIL OVERTEMPERATURE - TROUBLESHOOTING	101 - 104	Dec. 30/2023
71-00-06	814-811-A01	MAINT XX1X - ENGINE PARAMETER OUT OF LIMIT - T4.5 OVERTEMPERATURE IN FLIGHT - TROUBLESHOOTING	101 - 104	Dec. 30/2020
71-00-06	814-812-A01	PARAMETER INSTABILITY - TORQUE - TROUBLESHOOTING	101 - 106	Dec. 30/2021
71-00-06	814-815-A01	LOSS OR FLUCTUATION OF NF INFORMATION - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	814-816-A01	MAINT XX8X - FUEL TEMPERATURE EXCEEDANCE - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	814-817-A01	LOGID: X8XX AND MAINT: X1XX - OIL OVERPRESSURE - TROUBLESHOOTING	101 - 104	Dec. 30/2023
71-00-06	814-818-A01	MAINT X4XX - OIL FLOW INTERRUPTION - TROUBLESHOOTING	101 - 104	Dec. 30/2023
71-00-06	814-825-A01	OIL FILTER PRECLOGGING INDICATION - TROUBLESHOOTING	101 - 102	June 15/2023
71-00-06	814-830-A01	THE FIRE WARNING LIGHT COMES ON - TROUBLESHOOTING	101 - 102	June 15/2021
71-00-06	814-831-A01	LOGST: 4XXX - ENGINE PARAMETER OUT OF LIMIT - N2 OVERSPEED DETECTED - TROUBLESHOOTING	101 - 102	Dec. 30/2022
71-00-06	814-832-A01	LOGST: 8XXX - OVERSPEED NOT AVAILABLE - TROUBLESHOOTING	* 101 - 102	June 15/2024
71-00-06	815-801-A01	UNUSUAL NOISES DURING RUNDOWN PHASE - TROUBLESHOOTING	101 - 108	Dec. 30/2022
71-00-06	815-802-A01	MAINT XX2X - RUNDOWN TIME OUT OF LIMITS - TROUBLESHOOTING	101 - 112	Dec. 30/2022
71-00-06	815-804-A01	LOW FUEL PRESSURE LIGHT REMAINS OFF - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	815-805-A01	LOW OIL PRESSURE LIGHT REMAINS OFF - TROUBLESHOOTING	101 - 104	Dec. 30/2021

* Page modified following update No. 28

SAFRAN HELICOPTER ENGINES

ARRIEL 2 D

MAINTENANCE MANUAL

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	815-806-A01	POWER TURBINE BLOCKED - TROUBLESHOOTING	101 - 102	Dec. 30/2019
71-00-06	816-801-A01	SMOKE FROM EXHAUST PIPE - TROUBLESHOOTING	101 - 108	Dec. 30/2021
71-00-06	816-804-B01	LEAK AT THE AIRCRAFT DRAIN CLUSTER - TROUBLESHOOTING	101 - 104	Dec. 30/2023
71-00-06	816-804-C01	LEAK AT THE AIRCRAFT DRAIN CLUSTER - TROUBLESHOOTING	101 - 104	Dec. 30/2023
71-00-06	816-804-D01	LEAK AT THE AIRCRAFT DRAIN CLUSTER - TROUBLESHOOTING	101 - 106	Dec. 30/2023
71-00-06	816-804-E01	LEAK AT THE AIRCRAFT DRAIN CLUSTER - TROUBLESHOOTING	101 - 106	Dec. 30/2023
71-00-06	816-806-A01	FUEL FILTER VISUAL BLOCKAGE INDICATOR POPPED OUT - TROUBLESHOOTING	101 - 102	June 15/2022
71-00-06	816-806-B01	FUEL FILTER VISUAL BLOCKAGE INDICATOR POPPED OUT - TROUBLESHOOTING	101 - 102	June 15/2022
71-00-06	816-807-A01	FUEL DILUTION RATE IN OIL NOT COMPLIANT - TROUBLESHOOTING	101 - 102	June 15/2021
71-00-06	816-808-A01	INCORRECT OPERATION OF ONE OF THE IGNITION DEVICE LINES - TROUBLESHOOTING	101 - 102	Dec. 30/2021
71-00-06	816-811-A01	ABNORMAL OIL CONSUMPTION - TROUBLESHOOTING	101 - 110	Dec. 30/2023
71-00-06	816-811-B01	ABNORMAL OIL CONSUMPTION - TROUBLESHOOTING	101 - 110	Dec. 30/2023
71-00-06	816-812-A01	CHECK OF ABNORMAL OIL PRESSURE - TROUBLESHOOTING	101 - 106	May 30/2011
71-00-06	816-814-A01	OIL LEAKAGE BETWEEN M03 AND M04 - TROUBLESHOOTING	101 - 104	June 15/2021
71-00-06	816-817-A01	ENGINE POWER CHECK - INCORRECT MARGIN - TROUBLESHOOTING	101 - 124	June 15/2021
71-00-06	816-824-A01	MAINT: 1XXX - EDR PARAMETER CONFIGURATION - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	816-825-A01	OIL LEAK AT BLEED VALVE OR AIR INTAKE - TROUBLESHOOTING	101 - 102	June 15/2023

* Page modified following update No. 28

List of Effective Pages

71

Page 4
June 15/2024

SAFRAN HELICOPTER ENGINES

ARRIEL 2 D

MAINTENANCE MANUAL

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	816-827-A01	OIL LEAKAGE OF THE POWER DRIVE OF THE STARTER - TROUBLESHOOTING	101 - 102	June 15/2021
71-00-06	816-829-A01	INCORRECT PURGE TEST OF THE INJECTION WHEEL PURGE VALVE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-801-A01	FAIL1X: XXX2 - WATCHDOG FAIL A - TROUBLESHOOTING	101 - 102	May 30/2011
71-00-06	817-803-A01	FAIL1C: XX8X - RUDDER PEDAL - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-808-A01	FAIL2C: XX2X - AIRCRAFT STOP/IDLE/ FLIGHT POSITION FAULT - TROUBLESHOOTING	101 - 104	Dec. 30/2023
71-00-06	817-810-A01	FAILX: XX2X - T0 INCONSISTENCY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-823-A01	FAIL1C: XX2X - COLLECTIVE PITCH 1 - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-824-A01	FAIL1C: XX4X - COLLECTIVE PITCH 2 - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-825-A01	FAIL1C: XXX2 - TOT (T4) FAIL 1 - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-826-A01	FAIL1C: XXX4 - TOT (T4) FAIL 2 - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-828-A01	FAIL2X: XXX8 - T0 FAIL A - TROUBLESHOOTING	101 - 106	June 15/2019
71-00-06	817-833-A01	FAIL1C: X1XX - P3 FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2018
71-00-06	817-842-A01	FAIL1C: XXX8 - RAW TORQUE FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-844-A01	FAIL1X: XX8X - TOT (T4) CONFORMATION FAIL A - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	817-847-A01	FAIL1X: X1XX - TORQUE CONFORMATION FAIL A - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	817-861-A01	FAIL1X: XXX1 - EECU INTERNAL FAILURE A - TROUBLESHOOTING	101 - 102	Dec. 30/2021
71-00-06	817-864-A01	FAIL1C: X2XX - P3 DRIFT - TROUBLESHOOTING	101 - 106	June 15/2021

* Page modified following update No. 28

SAFRAN HELICOPTER ENGINES

ARRIEL 2 D

MAINTENANCE MANUAL

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	817-869-A01	FAIL2X: XXX4 - P0 EECU A - TROUBLESHOOTING	101 - 102	Dec. 30/2021
71-00-06	817-874-A01	FAILX: X2XX - P0/P3 INCONSISTENCY - TROUBLESHOOTING	101 - 102	Dec. 30/2021
71-00-06	817-878-A01	FAIL2C: X4XX - FUEL VALVE RESOLVER FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-880-A01	FAIL1X: 1XXX - STEPPER MOTOR FAILURE - TROUBLESHOOTING	101 - 110	Dec. 30/2022
71-00-06	817-884-A01	FAIL2C: X1XX - BLEED VALVE ANOMALY - TROUBLESHOOTING	101 - 106	June 30/2018
71-00-06	817-906-A01	FAIL1X: 2XXX - EECU / AIRCRAFT CONFIGURATION INCONSISTENCY A - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	817-907-A01	FAIL1A: XXX8 - N2 FAILURE ON CHANNEL A OR FAIL2A: XX1X - N2 OVERSPEED ACQUISITION FAILURE ON CHANNEL A - TROUBLESHOOTING	101 - 104	Dec. 30/2022
71-00-06	817-910-A01	FAIL2C: XX1X - EECU INTERNAL CROSS TALK FAILURE - TROUBLESHOOTING	101 - 102	Dec. 30/2021
71-00-06	817-912-A01	FAIL1B: XXX8 - N2 FAILURE ON CHANNEL B OR FAIL2B: XX1X - N2 OVERSPEED ACQUISITION FAILURE ON CHANNEL B - TROUBLESHOOTING	101 - 104	Dec. 30/2022
71-00-06	817-915-A01	FAILX: XXX2 - N2 INCONSISTENCY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-918-A01	FAIL1A: XXX4 - N1 FAILURE (ALTERNATOR A ON THE HARNESS) - TROUBLESHOOTING	101 - 104	June 15/2020
71-00-06	817-919-A01	FAIL1B: XXX4 - N1 FAILURE (ALTERNATOR B ON THE HARNESS) - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-920-A01	FAILX: XXX1 - N1A / N1B INCONSISTENCY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-928-A01	FAIL1X: XX1X - HELICOPTER P0 FAILURE A - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	817-929-A01	FAIL1A: X8XX - ARINC FAILURE A - TROUBLESHOOTING	101 - 104	June 15/2020
71-00-06	817-932-A01	FAIL1A: X4XX - ALTERNATOR FAILURE A - TROUBLESHOOTING	101 - 104	Dec. 30/2021

* Page modified following update No. 28

List of Effective Pages

71

Page 6
June 15/2024

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	817-933-A01	FAIL1B: X4XX - ALTERNATOR FAILURE B - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-938-A01	FAIL1X: X2XX - 28 V FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-947-A01	FAILX: XX1X - P0 INCONSISTENCY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-949-A01	FAIL2C : X2XX - STOP ELECTRO-VALVE FAILURE - TROUBLESHOOTING	101 - 104	June 30/2018
71-00-06	817-966-A01	FAIL2C: XX4X - OUT OF NEUTRAL POSITION SWITCH - TROUBLESHOOTING	101 - 104	Dec. 30/2020
71-00-06	817-976-A01	FAIL1B: X8XX - ARINC FAILURE B - TROUBLESHOOTING	101 - 104	June 15/2020
71-00-06	817-978-A01	FAILX: XXX4 - TOT (T4) SENSOR 1 / TOT (T4) SENSOR 2 INCONSISTENCY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	817-979-A01	FAILX: XXX8 - COLLECTIVE PITCH 1 / COLLECTIVE PITCH 2 INCONSISTENCY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-887-A01	FAIL1C: 1XXX - EECU TEMPERATURE SENSOR FAILURE - TROUBLESHOOTING	101 - 102	Dec. 30/2021
71-00-06	818-888-A01	FAIL1C: XX1X - TORQUE DRIFT FAULT - TROUBLESHOOTING	101 - 106	June 15/2023
71-00-06	818-889-A01	FAILX: 4XXX - FUEL FLOW DATUM INCONSISTENCY - TROUBLESHOOTING	101 - 102	Dec. 30/2022
71-00-06	818-890-A01	FAIL1C: XXX1 - N2 TORQUE FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-891-A01	FAIL2C: XXX4 - OIL PRESSURE FILTER INPUT FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-892-A01	FAILX: XX8X - OIL PRESSURE FILTER INPUT / OUTPUT INCONSISTENCY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-893-A01	FAIL2C: XXX8 - OIL PRESSURE FILTER OUTPUT FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-894-A01	FAIL1C: X8XX - OIL TEMPERATURE FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-895-A01	FAIL2C: XXX1 - FUEL PRESSURE FILTER INPUT FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021

* Page modified following update No. 28

SAFRAN HELICOPTER ENGINES

ARRIEL 2 D

MAINTENANCE MANUAL

<u>Chapter Section Subject</u>	<u>Task</u>	<u>Title</u>	<u>Pages</u>	<u>Date</u>
71-00-06	818-896-A01	FAILX: XX4X - FUEL PRESSURE FILTER INPUT / OUTPUT INCONSISTENCY - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-897-A01	FAIL2C: XXX2 - FUEL PRESSURE FILTER OUTPUT FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-898-A01	FAIL1C: X4XX - FUEL TEMPERATURE FAILURE - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-899-A01	MAINT: 0800 - EDR FAIL - TROUBLESHOOTING	101 - 104	Dec. 30/2021
71-00-06	818-901-A01	FAIL2X: XXX2 - EDR DATA INVALID A - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	818-903-A01	FAIL1X: XX2X - T0 HELICOPTER A - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	818-905-A01	FAIL1X: XX4X - N2 DATUM FAIL - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	818-906-A01	FAILX: X1XX - N2 DATUM INCONSISTENCY - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	818-907-A01	FAIL2C: XX8X - AUXILIARY MODE FAULT - TROUBLESHOOTING	101 - 102	Dec. 30/2021
71-00-06	818-908-A01	FAIL1X: 4XXX - INST LOSSES A - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	818-910-A01	FAIL1X: 8XXX - PWR OFF-TAKE A - TROUBLESHOOTING	101 - 102	June 15/2020
71-00-06	818-912-A01	FAIL2X: XXX1 - HELICOPTER DATA INVALID A/B - TROUBLESHOOTING	101 - 102	Dec. 30/2020
71-00-06	818-913-A01	FAILX: X4XX - QUICK P3 DRIFT - TROUBLESHOOTING	101 - 102	June 15/2021
71-00-06	818-914-A01	FAILX: X8XX - SLOW P3 DRIFT - TROUBLESHOOTING	101 - 102	June 15/2021
71-00-06	818-922-A01	FAIL2A: XX2X AND/OR FAIL2B: XX2X - EECU BUILT-IN TEST OVERSPEED FAILURE - TROUBLESHOOTING	* 101 - 104	June 15/2024
71-00-06	818-938-A01	RED GOV LIGHT OR AMBER GOV LIGHT OR FLASHING AMBER GOV LIGHT - TROUBLESHOOTING	* 101 - 102	June 15/2024

* Page modified following update No. 28

List of Effective Pages

Page 8

71

June 15/2024