

WORK ORDER CONTROL SHEET

Works Order No:	<del>SB/EC120B/18/02/0027</del> <del>9M-HFA</del>	Date Open:	2 FEB 2018	Date Completed:	19-2-18
Aircraft Registration:	9M-HFA	Aircraft Type:	EC120B	Total A/F Hours:	894:53
Raised By:	NAZURAH	Aircraft S/No.	<del>1487</del>	Total Landing:	1328

Description of Work

TO CARRY OUT IDENTIFICATION OF PART AND SERIAL NUMBER FROM FRONT AND REAR ELECTRICAL MAGNETIC PLUGS AS PER SAFRAN ARRIUS 2F SB A319 79 4840 § 2.3.

Action Taken

MANDATORY ALERT SB A319-79-4840 VERSION A CARRIED OUT AS PER DETAILS BELOW. PARA 2.1 & 2.2

A) ELECTRICAL MAGNETIC PLUG POSITION A (REAR ITEM 79-38-00-01-00)  
PN: ~~9520011645~~; S/N: ~~0090673~~

B) ELECTRICAL MAGNETIC PLUG POSITION B (FWD-ITEM 79-38-00-01-010)  
PN: ~~9520011645~~; S/N 1091

PARA 2.3; BOTH POSITION A & POSITION B MAGNETIC PLUGS ~~ARE NOT CONCERNED~~ BY THIS ASB DUE TO ~~DIFFERENT PART NUMBERS~~.

Man	Hrs	Total Man Hrs	LAE Name	Signature	Lic./Auth. No.
			ARIFF		

Description	Part Number	Serial Number On	Serial Number Off	Qty.	Batch Number
-	-	-	-	-	-

Duplicate Inspection in accordance with DCA AN 51

1 <sup>st</sup> Insp.	Lic./Auth. No.	Date	2 <sup>nd</sup> Insp.	Lic./Auth. No.	Date
N/A	N/A	N/A	N/A	N/A	N/A

Date	Closed By	Signature	Lic/Auth No.	Next Due Date	Next Due Hrs/Landing
21/02/2018	-	-	-	-	-

The work recoded above has been carried out in accordance with the requirements of MCAR for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.