


DELIVERY NOTE WP

DELIVER TO :

GALAXY AEROSPACE (M) SDN. BHD.
 CAMO DEPARTMENT
 Lot 11, MRO Centre,
 Malaysia International Aerospace Centre,
 Sultan Abdul Aziz Shah Airport,
 47200 Subang, Selangor
 Malaysia.
 Attn : Zaty Nadhira binti Mohamed Zuhari

DN NUMBER : GAM/DN/BOB/20-111
OUR REFERENCE : WP-BOB-20-2665
WO REFERENCE : GAM-WO-20-2665
DATE COMPLETION: 24 DECEMBER 2020
AJL NUMBER : 000344

A/C DETAILS							
A/C TYPE	A109E	A/C REG	9M-BOB	A/C S/N	11212		
OWNER / OPERATOR	FIRE AND RESCUE DEPT. OF MALAYSIA	A/C TOTAL TIME	3476:48	LANDINGS	3545		
ENGINE #1 S/N	PCE-BC0359	T.S.N	3476:48	T.S.O	-		
ENGINE #2 S/N	PCE-BC0358	T.S.N	2680:18	T.S.O	-		
LIST OF TASK PERFORMED	WP NUMBER	NUMBER OF PAGES					
		*WS	*PR	*ARC	*S	*SBC	*OTH
SB109EP-173 PART I	001	1	1	-	-	1	-
*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. AS ABOVE.							
NAME	NURUL LYANA MUHAMAD	SIGNATURE		DATE	29 DECEMBER 2020		
VERIFIED AND ACCEPTED BY				MUHAMMAD IHSAN MASRI CAMO Planner Galaxy Aerospace (M) Sdn. Bhd. (1040262-D)			
DATE				29/12/2020			

- *WS – WORKSHEET
- *PR – PART REPORT
- *ARC – AUTHORISED RELEASE CERTIFICATE
- *S – SERVICEABLE LABEL
- *SBC – SERVICE BULLETIN COMPLIANCE
- *OTH – OTHERS

WORK ORDER

To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia
 International Aerospace Centre, SAAS Airport,
 Subang
 Malaysia

Attention: Mr. Syafrul Yamani
 Engineering Manager
 syafrul@galaxy aerospace.my

Work Order Number: GAM-WO-20-2665

Work Pack Reference: WP-BOB-20-2665

Date Issued: 24/12/2020

A/C Registration / SN: 9M-BOB/11212

Sheet: 1 of 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	SB109EP-173 PART I (EASA AD NO.: 2020-0256)		<u>3.0</u> (PLEASE ADVISE)

DUE AT 3564:42 FH

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.



Thank you.
 Best Regards,



Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Management Manager
 Email: zaty@galaxy aerospace.my

CLIENT/OWNER: FIRE AND RESCUE DEPT. OF MALAYSIA AIRCRAFT TYPE: A109E REGISTRATION: 9M-BOB BASE/FACILITY: SUBANG DATE IN: 24/12/2020 OUT: 24/12/2020	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: WP-BOB-20-2665-001 WORK/INSP/DESC: SB109EP-173 PART I WORKPACK REF: WP-BOB-20-2665 LBE REF NO.: NOT APPLICABLE SHEET: 1 OF 1	
	AIRCRAFT	11212	3476:48	3545		
	#1 ENGINE:	PCE-BC0359	3476:48	N/A		N/A
	#2 ENGINE:	PCE-BC0358	2680:18	N/A		N/A
			NG / N1	NF / N2		

Reason for raising: SB109EP-173 PART I (EASA AD NO.: 2020-0256) TO BE CARRIED OUT I.A.W JBPM.CAMO.AMP.A109E ISSUE 1 REV 0 DATE 21 JAN 2020	Raised by and date: Muhammad Ihsan Masri 24/12/2020	Other requirements/information: NIL
--	---	--

Item	Description	Technician	* Eng. CRS	Date
1	SB109EP-173 PART I (EASA AD NO.: 2020-0256) ATA 53 - CENTRAL FUSELAGE FRAME ASSY AT STA 1815, INSPECTION AND REPAIR OF TO PERFORM INSPECTION TO DETECT CRACKS IN THE CENTER FUSELAGE AT INTERSECTION OF LATERAL PYLON (LH AND RH SIDE) WITH FLOOR SPAR NOTES: THE HELICOPTERS POSTS THAT HAVE BEEN REPAIRED IN ACCORDANCE WITH PART II (LH SIDE) OR PART III (RH SIDE) OF THIS SERVICE BULLETIN, OR IN ACCORDANCE WITH REPAIR DRAWING P/N 109-0952-67-117 (LH SIDE) OR P/N 109-0952-67-102 (RH SIDE), SHALL BE INSPECTED IN ACCORDANCE WITH PART I AFTER THEY HAVE ACCUMULATED MORE THAN 1000 FH OF 3500 LANDINGS SINCE REPAIR NOTES: PART II AND PART III SHOULD BE CARRIED OUT BEFORE THE NEXT FLIGHT AFTER THE CRACKS ARE FOUND DURING COMPLIANCE WITH PART I OF THE SERVICE BULLETIN. REF: SB109EP-173 (EASA AD NO.: 2020-0256) REMARKS: CARRIED OUT FOUND SATISFACTORY		 	24/12/2020

- *The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.
- *The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK WHERE APPLICABLE

PART LABELLED & RETURNED	DD SHEET	DUPICATED INSP	GROUND RUN	FLIGHT TEST	PACKAGE CHK	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING EFFECTS	DATE UPDATE	STATUS URGENT	DD STATUS	MR PART LOG BOOK	ENGINE OILY BLOCK	PROPPELLER LOG BOOK	WPI CARD	GEN CLAMP LOG CARD	MISC RELATED BOOK
--------------------------	----------	----------------	------------	-------------	-------------	----------------------	------------------	------------------	-------------	---------------	-----------	------------------	-------------------	---------------------	----------	--------------------	-------------------

CLIENT/OWNER: FIRE AND RESCUE DEPT. OF MALAYSIA AIRCRAFT TYPE: A109E REGISTRATION: 9M-BOB BASE/FACILITY: SUBANG DATE IN: 24/12/2020 OUT: 24/12/2020	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO:	WP-BOB-20-2665-001
	AIRCRAFT	11212	3476 : 48		3545	
	#1 ENGINE:	PCE-BC0359	3476 : 48		N/A	N/A
	#2 ENGINE:	PCE-BC0358	2680 : 18		N/A	N/A
			NG / N1	NF / N2	SHEET:	1 OF 1

Reason for raising: SB109EP-173 PART I (EASA AD NO.: 2020-0256) TO BE CARRIED OUT I.A.W JBPM.CAMO.AMP.A109E ISSUE 1 REV 0 DATE 21 JAN 2020	Raised by and date: Muhammad Ihsan Masri 24/12/2020	Other requirements/information: NIL
--	---	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
(This table area is currently blank with a diagonal line drawn across it.)									

NAME	FIRM	SIGN & APPROVAL	DATE
	GAM		24/12/2020

- *The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.
- *The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK WHERE APPLICABLE

PARTS ORDERED & RETURNED	ISS. PARTS	DISPATCH INSP	PROVIDE PART	RIGHTS TEST	TURBO CHG	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIRTY UPDATE	STATUS UPDATE	OLD STATUS	AIRCRAFT LOGBOOK	ENGINE OIL	PROPELLER LOGBOOK	LOG CARD	QUALITY ASSURANCE LOGS/APP	MISC RECORDS DATA
--------------------------	------------	---------------	--------------	-------------	-----------	----------------------	------------------	-------------------	--------------	---------------	------------	------------------	------------	-------------------	----------	----------------------------	-------------------

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date: 24/12/2020	
	Number: SB 109EP - 173		
	Revision: -		


Customer Name and Address: GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.	Telephone: +603 7734 7226
	Fax: +603 7734 7526
	B.T. Compliance Date: 24/12/2020

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
A109E	11212	1	3476:48	-

Remarks:

SB 109EP-173 PART 1 CARRIED OUT AND COMPLETED FOUND SATISFACTORY.

[Signature]



Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.